MAR 1 6 1994

LAND CORNER RECORDATION CERTIFICATE 1994 FEB 14 AM 10: 14 Filing Requirement of Act 74, Mich. P.A. 1970

| i | . | ËĊ | | • | |
|---|----------|----|--|---|--|
| | | | | | |

For corners in COMMISSION

| FRIENISHIP TOWNSHIP 1. Public Land Survey 2. Property Controlling 3. T. R. 2. Property Controlling 3. T. R. 3. Miscellaneous 3. T. R. 4. Lot No. 3. Recorded Plat 4. Lot No. 4. Lot No. 5. Private Claims A December 4. Lot No. 6. Recorded Plat 5. Private Claims A December 6. December 6. Lot No. 6. Recorded Plat 6. December 7. December 7. December 8. December 9. December | .— | EMMET (County) | Located Ir | | _ Corner Code | # . | Lill | na | A. L | lipe | | | |
|---|------|---|--|---|--|--|---------------------------|--|--------------------------------------|---------------------|--|----------|-------------|
| ECRP # 26 | | <u>.</u> | | | | | | | 6 | / | | | |
| 2. Property Controlling S T R R Sidestion S T R R Sidestin Sidesti | ι. | • | - r | | | | | LIBER | | 4 | | | |
| 2. Property Controlling S T R In Section S T R 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No. Recorded Plat 5. Private Claims 6. Recorded Plat 7. Recorded Plat 7. Recorded Plat 7. Recorded Plat 8. Register of Deeds Stamp & File Number 8. Register of Deeds Stamp & File Numb | | ECRP # 26 | , T | | | | | PAGE | | 8_ | • | | |
| 3. Miscellaneous S. T. R. Register of Deeds Stamp & File Number Property in Sec. S. T. R. Recorded Plat 4. Lot No. Recorded Plat 5. Private Claims Richard E. Oelke in a field survey on 28 December 19 4. A 3 C. D. F. F. O. H. L. K. L. Recorded Plat Richard E. Oelke in a field survey on 28 December 19 4. A 3 C. D. F. F. O. H. L. K. L. Recorded Plat Richard E. Oelke in a field survey on 28 December 19 4. A 3 C. D. F. F. O. H. L. K. L. Recorded Plat In the State Plat Plat Plat Plat Plat Plat Plat Plat | 2. | · - | S T | R | | | | | | | | | |
| 4. Lot No | 3. | = - • | S T | R | | | Register of | Deeds | Stamo | & File | Nor | her | |
| Richard E. Celke Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke Richard E. Celke In a held survey on 28 December Richard E. Celke In a held survey on 28 December Richard E. Celke Richard E. Celke In a held survey on 28 December Richard E. Celke Richard E. Celke Richard E. Celke In a held survey on 28 December Richard E. Celke Richard E. Celke Richard E. Celke Richard E. Celke In a held survey on 28 December Richard E. Celke | | Property in Sec. | S T | R | - | | | | | | | | |
| Richard E. Oelke In a field survey on 28 December 19 34 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of year decree of a count of Lank additionation of the Michigan Board of Land Survey not or by a Decree of a count of Lank additionation of Lank and or that the corner points mentioned in less 3,4 and 5 acres were in conformance with the rules of the Michigan Board of Land Survey not or by a Decree of a count of Lank additional county of Lank and the La | | | | | | | — д в | С р | E F | G H | IJ | ĸ i | L |
| Richard E. Oelke in a fliet survey on 28 December 93 do herby certify that under requirements of 12.75 Michigan P.A. of 1970, the conserve not mentioned in lings 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of the decreated of Land Survey row decree of a Count of Law, address that the corner points mentioned in less 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Survey or or by a Decree of a count of Law, address that the corner points mentioned in less 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a count of Law, address that the corner points of Land Surveyors or by a Decree of a count of Law, address that the corner points of Land Surveyors or by a Decree of a count of Law, address that the Corner points of Land Surveyors or by a Decree of a count of Law, address that the Corner points of Land Survey or by a Decree of a count of Law, address that the Corner points of Land Survey or by a Decree of a count of Law, address that the Corner points of Land Survey for Survey fo | Э. | Private Claims | | | | | | —— <u>Ş</u> – | | 3- | T | | Ţ |
| A Description of original monument and accessories and/or subsequent restoration. NoTE: Not more than 4 corners 13,18,19, 4 24, 1389, RTN -1380 | | ; . m taka a d m ana | , | | , | | | | + + | + | | + | + |
| in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Survey of the United States Department of the interior, Survey of the United States Department of the interior, Survey and States and Sabove were in conformance with the rules of the Michigan Board of Land Survey as of yu Becrea of a Court of Law, established, monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-7, Section corner 13, 16, 19, & 24, T36M, R7M -1480 | l, _ | | , in a field survey on | | | , 19 , | Fi | T i | | 110 | 1-11 | | 1 |
| Management or by a decree of a Court of Law and/or that the corner points mentioned in times 3.4 and 5 above were in conformance with the relies of the Michigan Board of Land Suveyors of by a Bornes of 3 below the relies of the Michigan Board of Land Suveyors of by a Bornes of 3 of the conformation on the relies of the Michigan Board of Land Suveyors of by a Bornes of 3 of the conformation on this certificate. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: **Note Corner 13, 18, 19, & 24, 1388, 878* **Note Corner 13, 18, 19, & 24, 1388, 878* **Note Corner 13, 18, 19, & 24, 1388, 878* **Note Corner 14, 19, \$ 24, 1388, 878* **India Survey for S | in | lines 1 and 2 above wer | re in conformance with reg | gulations and re | ules therefore as | required in the | Γï | | 16- | 15 | 1-14 | +- | 3- |
| Court of Law, established, re-established, monumented, re-monumented, re-covered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: H-7, Section corner 13,16,19, & 24, T59H, RTW -1840 GLO Set cadar poet N81*M, 681ke, 4" baln & 359*E, 76 lks, 4" cherry 3.1850 Irish Survey for Swift, rfd 1/2" tron pipe1950 Irish Survey for Swift, rfd 1/2" tron pipe1951 Irish Survey for Swift, rfd 1/2" tron pipe1971 BAY Work drawing shows corner as witnessed in 1976 by RE81971 BAY Work drawing shows corner as witnessed in 1976 by RE81971 Green Survey for Bank of Alna, shows 3/8" fron pipe1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed1988 Online Plat of Cedars 310ff, as recorded. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: N-7, Section corner 13,16,19, 4 24, T39N, R7N Found 3/8" fron pipe, 3" long, .3" below the surface1987 N3-4", 59.92", fd (4), 4" maple old natil in NM face Si55*E, 193.92", fd (4), 4" maple old natil in NM face Si55*E, 59.92", fd (4), (1)(3), 10" maple old natil in NM face Si54*E, 59.92", fd (1)(3), 10" maple old natil in NM face Si54*E, 59.93", 10" maple old natil in NM face Si54*E, 59.93", 10" maple old natil in NM face Si54*E, 59.93", 10" maple old natil in NM face Si54*E, 59.93", 10" maple old natil in NM face Si54*E, 100.08", 14" w. birch tagged 23383 in SE face Si54*E, 100.08", 14" w. birch tagged 23383 in NF face NS1*E, 100.08", 14" w. birch tagged 23383 in NF face NS1*E, 10" MS1*E, 10" M | | | | | | | | 1 | 1 1 | 1 | 23 | | 1 |
| NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. M-7, Section corner 13, 18, 19, 8, 24, T36N, RTM -1840 GL0 Set codar post N811M, 651ke, 4" beln & S19°E, 78 1ka, 4" cherry 1800 Schweighert Fd. Iron pipe (1) N33°E, 51, 2', 9" maple; (2) N51°M, 80, 2', 10" maple1985 Irish Survey for Swift. fd 1/2" iron pipe1986 M. Feinful Unrecorded Plat of Hybhaven shows found iron1971 Statum Long, Liber 1, page 213, Fd. 2', 8" maple (2) N51°M, 80, 2', 10" maple1987 Green Survey for Bank of Alna, shows 3/8" iron pipe. (3) N35°E, 59.99', 8" maple -1987 Green Survey for Bank of Alna, shows 3/8" iron pipe as witheast on 1998 Statum Long, Liber 1, page 213, Fd. 3/2" iron pipe. (3) N35°E, 59.99', 8" maple -1987 Green Survey for Bank of Alna, shows 3/8" iron pipe as witheast on 1998 Statum of Corner evidence found and/or method applied in restoring or reestablishing corner. M-7, Section corner 13, 16, 19, 4 24, T3SM, RTM Found 3/8" iron pipe, 3' long, 3' below the surface. N34°E, 59.92', fd (4), 14" maple old natil in NM face S58°E, 59.92', fd (4), 4" maple old natil in NM face N51°M, 80.48', fd (2) 16" maple no natil or beep CELKE N51°M, 80.48', fd (2) 16" maple no natil or beep COEKE N51°M, 80.48', fd (2) 16" maple no natil or beep S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', fd (4), 14" maple old natil in NM face S58°E, 59.02', | | | | - | • | • | 9 | ↓ Ï | 1-1 | ΨÏ | | | 1 |
| On this certificate. A. Description of original monument and accessories and/or subsequent restoration: N-7, Section corner 13,18,19, & 24, 738N, R7W 1840 GLD Set cectar poet 1850 Schweighert Fd. Fron pipe (1) N33*E, 81.2', 9" maple; (2) M51*M, 80.2', 10" maple. 1950 Schweighert Fd. Fron pipe (1) N33*E, 81.2', 9" maple; (2) M51*M, 80.2', 10" maple. 1958 M. Feindt 1978 Bidetrup 1971 Green 1977 Green 1978 Green 1987 Green Survey for Bank of Alna, shows 3/8" fron pipe as witnessed. 1980 Oilke Plat of Gedar Bluff, as recorded. 1980 Oilke Plat of Cedar Bluff, as recorded. 1980 Oilke Plat of Cedar Bluff, as recorded. 1980 Oilke Plat of Cedar Bluff, as recorded. N-7, Section corner 13,18,19, & 24, T38N, R7W Found 3/8" fron pipe, 3' long, .3' below the surface. N51*M, 80.48", fd (2) 18" maple old nail in NW face S38*E, 69.02", fd (1)(3), 10" maple old nail in NW face N51*M, 80.48", fd (2) 18" maple no nail or beep C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: N-7, Section corner 13,18,19, & 24, T38N, R7W At Desition of 3/8" fron pipe, so ta 2" diam., 30" long, 9" pe with a base sagnet and a standard brase RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face N34*E, 59.20", fd (1)(3), 10" maple old nail in NW face N34*E, 59.20", fd (1)(3), 10" maple old nail in NW face N34*E, 59.20", fd (1)(3), 10" maple old nail in NW face N34*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM5*Emet County Survey Resonumentation Program cap. 3' long, 3' below the surface. N34*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM4*E, 59.20", fd (1)(3), 10" maple old nail in NW face RM5*Emet County Survey Resonumentation Program cap. 3' long, 3' below the surface. N34*E, 59.20", fd (1)(3), 10" maple | | | | · | | , | 1030_ | 29- | 28 | 27 | 26 | | 25- |
| A. Description of original monument and accessories and/or subsequent restoration: M-7, Section corner 13,16,19, \$ 24, T38N, R7W -1840 GLO Set cedar post N81*W, 661ke, 4" baln & 559*E,76 lks, 4" cherry -1850 Schweighert Fd. iron pipe (1) N93*E, 61.2', 0" maple; (2) N51*W, 80.2', 10" maple1865 Irish Survey for Swift, fd 1/2" iron pipe1866 M. Feinatt Unrecorded Plat of Wynhawn shows found iron1871 BAY Work drawing shows corner as withressed in 1876 by REB1976 Sidetrup LCRG, Liber 1, page 213, fd. 3/8" iron pipe. (3) N35*E, 59.93', 14" maple -1987 Green Survey for Bank of Alna, shows 3/8" iron pipe as withressed1987 Green Survey for Bank of Alna, shows 3/8" iron pipe as withressed. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: N-7, Section corner 13,16,19, 4 24, T39N, R7W Found 3/8" iron pipe, 3' long, 3' ballow the surface | NC | | · | ne town and r | range, may be r | ecorded | | + | + | ++ | ╁╾┼ | \dashv | t |
| A. Description of original monument and accessories and/or subsequent restoration: H-7, Section corner 13, 18, 19, 8, 24, T38N, R7N 1840 1930 1930 1940 1950 1950 1950 1950 1950 1950 1950 195 | • | on this certifica | ite. | | | | " | 32- | 33- | 34 | 35 | + | 36- |
| -1840 GLO Sot codar post N81*M, 851ks, 4" ball & \$59*E, 75 lks, 4" cherry -1850 Schweighert Pd. iron pipe (1) N33*E, 51.2", 0" maple; (2) N51*M, 80.2", 10" maple. -1865 Irish Survey for Swifft, fd 1/2" iron pipe1866 N. Faindt Unrecorded Plat of Wynhaven shows found iron. -1871 SAY Work drawing shows corner as witnessed in 1976 by RES1976 Sidstrup LCRO, Liber 1, page 213, fd. 3/8" iron pipe1976 Sidstrup LCRO, Liber 1, page 213, fd. 3/8" iron pipe1987 Green Survey for Bank of Alma, shows 3/8" iron pipe as witnessed1987 Green Plat of Gadarayen, shows 1/8" iron pipe as witnessed. -1987 Green Plat of Cadar Bluff, as recorded. | A. | Description of origin | al monument and acces | ssories and/o | r subsequent re | storation: | | | - | | | | |
| Found 3/8" iron pipe, 3' long, .3' below the surface. N34"E, 59.92', fd (1)(3), 10" maple old nail in NW face 358"E, 69.02', fd (4), 14" maple old nail in SW face N51"M, 80.48', fd (2) 16" maple no nail or beep C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: N-7, Section corner 13,18,19, & 24, T36N, R7W At position of 3/8" iron pipe, set a 2" diam., 30" long, PVC pipe with a base magnet and a standard brase Emmet County Survey Remonumentation Program cap. 3' long, .3' below the surface. N34"E, 59.2', fd (1)(3), 10" maple old nail in NW face N34"E, 59.63', 10" maple agged 33983 in SE face S53"E, 100.08', 14" maple old nail in SW face 353"E, 100.08', 14" w. birch tagged #33983 in NW face N52"H, 76.03', 12" w. birch tagged #33983 in NW face N51"W, 80.48', fd (2) 16" maple no nail or beep Signed by Lichaeo E. Caller Date 14 January 1994 | | -1971 B&Y -1971 Bidstrup -1976 Bidstrup - - -1987 Green -1993 Oelke | tt Unrecorded Plat o Work drawing show Plat of Gaehaven, LCRG, Liber 1, pa Survey for Bank o Plat of Gedar Blu | f Wynhaven s s corner as shows fd 3/ ge 213, fd. f Alma, show ff, as recor | thows found inc witnessed in 1 (8" iron pipe. 3/8" iron pipe (s 3/8" iron pi ded. | 976 by REB. (3) (4) (5) pe as witness | \$55°E, N34°W, aed. | 69.09 | ', 14" | maple | | | |
| N34*E, 59.92', fd (4), 14' maple old nail in NW face S55*E, 69.02', fd (4), 14' maple old nail or beep C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-7, Section corner 13,18,19, & 24, T36N, R7W At position of 3/8' from pipe, set a 2" diam., 30" long, PVC pipe with a base magnet and a standard brase Emet County Survey Remonumentation Program cap. 3' long, 3' below the surface. N34*E, 59.92', fd (1)(3), 10' maple old nail in NW face N34*E, 59.02', fd (4), 14' maple old nail in NW face S53*E, 69.02', fd (4), 14' maple old nail in SW face S53*E, 100.08', 14'' N. birch tagged #33983 in SW face N55*W, 99.95', 12' w. birch tagged #33983 in NE face N55*W, 76.09', 12' oak tagged #33983 in NE face N51*W, 80.48', fd (2) 16'' maple no nail or beep Signed by Cather Date Annual 1994 | | N-7, Section corne | r 13,18,19, & 24, T36 | SN, R7W | | | | - C. | OF N | I E N | . | | |
| M-7, Section corner 13,18,19, & 24, T36N, R7W At position of 3/8" iron pipe, set a 2" diam., 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program cap. 3' long, .3' below the surface. N34*E, 59.92', fd (1)(3), 10" maple old nail in NW face N34*E, 59.63', 10" maple tagged 33983 in SE face 958*E, 69.02', fd (4), 14" maple old nail in SW face 953*E, 100.06', 14" w. birch tagged #33983 in SW face 959*W, 99.95', 12" w. birch tagged #33983 in NW face N52*W, 76.09', 12" oak tagged #33983 in NE face N51*W, 80.48', fd (2) 16" maple no nail or beep Signed by Carret Date 14 January 1994 | | N3 4° E, S58°E, | 59.92', fd (1)(3), 69.02', fd (4), 14" | 10" maple o maple old n | ld nail in NW ail in SW face | | | PF | OELI OFESS SURVE No 3398 | KE SIONAL YOR | Anoviano. | | |
| M-7, Section corner 13,18,19, & 24, T36N, R7W At position of 3/8" iron pipe, set a 2" diam., 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program cap. 3' long, .3' below the surface. N34°E, 59.92', fd (1)(3), 10" maple old nail in NW face N34°E, 59.63', 10" maple tagged 33983 in SE face 958°E, 69.02', fd (4), 14" maple old nail in SW face \$53°E, 100.06', 14" w. birch tagged #33983 in SW face \$559°W, 99.95', 12" w. birch tagged #33983 in NW face N52°W, 76.09', 12" oak tagged #33983 in NE face N51°W, 80.48', fd (2) 16" maple no nail or beep Signed by Characo E. Characo Date Annuary 1994 | С | Description of monu | ment for comer and acc | essories esta | blished to pero | etuate locatino | the position | n of the | corne | r: | | | |
| 32000 | | At posit Emmet Co N34°E N34°E S53°E S59°W N52°W | ion of 3/8" iron pipe unty Survey Remonumer , 59.92', fd (1)(3 , 59.63', , 69.02', fd (4), , 100.06', , 99.95', , 76.09', | e, set a 2" ontation Programme 10" maple to 14" maple to 14" w. birch 12" w. birch 12" oak tage | ram cap. 3' lo le old nail in agged 33983 in ld nail in SW ' t tagged #3398 n tagged #3398 ged #33983 in l | ng, .3' below NW face SE face Face In SW face In NW face | ith a base the surfa | magne' | t and : | a stan | idard | bras | is |
| 22000 | ۵. | | hea E O | V= | _ | . 14 \ | ANI) A A | 190 | 4 | | • | | |
| STANDARD CONTROL TO THE STANDARD TO THE STANDA | | • | | | [| Jate <u>IT</u> | ANUMEY | 117 | | | . - | | |