MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. _____ N.R. ____ 5 W.

			Emmet	COUNTY
DESCRIPTION OF CORNER 1/4 corner of	common to Sections 15	- 22		
CORNER MONUMENT Left iron in pla	ce			
DATE MONUMENT PLACED AND WITHESSED _	June 12, 1962			
WITHESSES TO CORNER				
	10" Tamarack	S 77 W	135.51	
	W. end culvert	N 40 W	29.51	
CIRCLE CORNER REGISTERED	Power pole	S 32 E	47.71	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of this area. Found large piece of iron (unidentifiable) and cedar stake below surface of road intersection E = W & N. Appears to be a corner of long standing and acceptance. Falls in line with fence south, and conforms okay for measurement east and west.

SURVEYOR'S SEAL

SIGNED Leweth J Ostling DATE June 14, 1962

REGISTERED KAND SURVEYOR

REGISTERED KAND SURVEYOR