SURVEY & REMONUMENTATION

MAR 1 3 2000

STATE OF MICHIGAN EMMET COUNTY RECORDED

SECTION		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970		
For corners in		in 017 (00 7 4), (all 01), 1 ,74.	•	
EMMET	Located In:	Corner Code #	Glenne A. Sijer	
(County)	READMOND		REGISTER OF DEEDS	
1. Public Land Survey ECRP #199	T <u>37N</u> R <u>6W</u>	G-3	LicenA	
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	S T R S T R S T R		PAGE 3/2	
4. Lot No, Reco	rded Plat		Register of Deeds Stamp & File Number	
I, Richard E. Oelke , in a that under requirements of P.A. 7 and 2 above were in conformance	field survey on 10 December 4, Michigan P.A. of 1970, the come with regulations and rules therefor the United States Department of	, 19 <u>99</u> _ do hereby certify er points mentioned in lines 1	A B C D E F G H I J K L M 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 12 13 13 17 14 13 17 14 13 17 18 18 18 18 18 18 18 18 18 18 18 18 18	
management or by a decree of a C and 5 above were in conformance	court of Law and /or that the corner with the rules of the Michigan Boalished, re-established, monumented	points mentioned in lines 3, 4	8 -19 - 20 - 21 - 22 - 23 · 24 · 9 · · · · · · · · · · · · · · · · ·	
NOTE: Not more that 4 comes on this certificate.	rs, all in the same town and ran	ge, may be recorded	11 - 32 - 33 - 34 - 35 36	
A. Description of original mon	nument and accessories and/or s	ubsequent restoration:		
Abstract: GLO set corr at centerline of State Rd., See back page for chronol	3 S. of Division Rd. It ha	Swenor set pk, O'Neill i as been used in subsec	found pk and replaced with 5/8" rod, juent surveys by local surveyors.	
B. Description of corner evidence	found and/or method applied in res	toring or reestablishing corner		
Found: at the intersection	on of Division and State Re 'x8"x1.5' granite rock, abo	oads, approximately 3' ove old glass, metal, le	below surface, the rotted remains of ather and another large stone. The was removed APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County R.E. CELLE	
C. Description of monument for co	rner and accessories established to	perpetuate locating the position	ECRP REP. 12.23.99	
Set: The granite rock not base magnet and a standa	ted above was removed, a rd brass Emmet County So	and replaced with a 2"	diameter, 30" long, PVC pipe with a n Program Cap, which was placed id faithful perpetuation of the position	
Additional Name			The state of the s	
Additional New Witness 1) N 67°E , 7 2) S 75°E, 3) S 39° W, 8 4) N 81°W, 2	79.31', pp, tagged 3 130.66', pp, tagged, 89.53', 8" pine, nail	3983, in SE face 30095, in S face SE face, added new na 30095, in the S face	RICHARD E. OELKE PROFESSIONAL SURVEYOR No. 33983	

0113510 Signed by _ Date _ 10 December 1999 Surveyor's Michigan License No. 33983

SURVEY & REMONUMENTATION

MAR 1 3 2000

PAGE 3/3

SECTION

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 199

37-6-G3

T37N R6W section corner bet. Secs. 3,4,9, 7 10 DIVISION and STATE ROADS

<u>Date</u>	Surveyor	Found	<u>Witnesses</u>		Notes	
1840	GLO	Set post	1) N 8	6°E 14L 8'	Beech	
			2) N 6	8°W 12L 9	' Beech	
1992	Swenor	set pk nail usi	ng ROW fences	to the SE		
1992	O'Neill	survey for Ira,	fd. Large PK na	il, replaced wit	h a 5/8" rerod, 3' S of Intersection	'n
			1) N 64°E,	79.86',	tag 30095 in power pole	
			2) S 76°E,	129.76',	tag 30095 in power pole	
			3) S 40°W,	86.25',	tag 30095 in 4" pine	
			4) N 80°W,	223.43',	tag 30095 in power pole	
1992	Swenor	fd. 5/8" rebar				
1997	Young	fd. 5/8" rebar				