





APR 2 9 1996

1995 DEC 19 PM 1:37

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Glenna a Sixa For corners in Corner Code # EMMET Located In: (County) Public Land Survey
 EMMET COUNTY REMON. CORNER #97 LIBER \_ 37 N R 6 W COMMON TO SECTIONS 2 & 3 Т т \_ PAGE ... R 2. Property Controlling s \_\_\_\_ T \_\_ in Section \_\_T \_\_\_\_R\_ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section \_ , Recorded Plat\_ 4. Lot No. 5. Private Claims DECEMBER 11 1, Michael A. Trowbridge , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 11....CORNER COMMON TO SECTIONS 2 & 3, T37N, R&W SEE EMMET COUNTY REMONUMENTATION PROGRAM CHRONOLOGY OF GLO CORNER ON BACK SIDE OF THIS PAGE. APPROVED LAND CORNER P.A. 345 OF 1990 Emport County BUES B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: 11.... FOUND 1/2" REROD WITH CAP 27463. THIS WAS SET AT STANDARD OFFSET AND ON LINE BETWEEN THE SOUTHWEST AND SOUTHEAST CORNERS

OF SECTION 35, T38N, R6M AS NOTED IN 1990 TROWBRIDGE LAND CORNER RECORDATION CERTIFICATE, LIBER 2, PAGE 317.

## FOUND WITHESSES

	3)	WEST	31.02'	5/8"	REROD	WITH	CAP	1136
--	----	------	--------	------	-------	------	-----	------

- 4) AZIMUTH 17° 47.94' POWER POLE (SPIKE IN WEST FACE)
- 5) AZIMUTH 82' 27.98' 10" MAPLE (SPIKE IN NORTH FACE)
- 6) AZIMUTH 116° 34.42' 8" MAPLE (SPIKE IN NORTH FACE)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11....THE 1/2" REROD WAS REMOVED AND REPLACED WITH A 2" DIAMETER X 30" LONG PVC PIPE, A BASE MAGNET AND A STANDARD BRASS EMMET COUNTY REMONUMENTATION CAP. THIS POSITION IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

31.02 EMMET COUNTY REMONUMENTATION MONUMENT

- 17' 47.94' POWER POLE (SET 27463 CAP AND NAIL IN WEST FACE) 4) AZIMUTH
- 5) AZIMUTH 82° 27.98' 10" MAPLE (SET 27463 CAP AND NAIL IN NORTH FACE)
- 6) AZIMUTH 116' 34.42' 8" MAPLE (SET 27463 CAP AND NAIL IN NORTH FACE)

Date Surveyor's Michigan License No.

OF MICK TROWBRIDGE NO. 27463
NO. 27463
NO. 27463
NO. 27463

Maria a maria

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

12/11/95

REVISED MAY 14, 1975

PAGE <u>88</u>

## EMMET COUNTY REMONUMENTATION PROGRAM

CHRONOLOGY OF GLO CORNER

REMON. CORNER #97

LCRC #37-06-11cc

TOWNSHIP...CROSS VILLAGE

CORNER COMMON TO SECTIONS 2 & 3, T37N, R6W

DATE	SURVEYOR	FOUND/SET	WITHESSES
1840	GLO	SET POST	1) S22°N 73 LINKS 20" SUGAR 2) S29°E 143 LINKS 12" SUGAR
1990	TROWERIDGE	SOUTHWEST AND SOUTH (SEE RECORDED SURVE	TANDARD OFFSET AND ON LINE BETWEEN THE EAST CORNERS OF SECTION 35, T38N, R6W Y, LIBER 278, PAGE 852). 3) WEST 31.02' 5/8" REROD WITH CAP 11360 4) AZIMUTH 17' 47.94' POWER POLE (SPIKE IN WEST FACE) 5) AZIMUTH 82' 27.98' 10" MAPLE (SPIKE IN NORTH FACE) 6) AZIMUTH 116' 34.42' 8" MAPLE (SPIKE IN NORTH FACE)
	SEE LAND CORNER	RECORDATION CERTIFI	CATE, LIBER 2, PAGE 317.