REMONUMENTATION

MAR 1 3 2000

STATE OF MICHIGAN EMMET COUNTY

99 DEC 28 AM 9: 35

LAND CORNER RECORDATION CERTIFICATE For corners in SECTION Filing Requirement of Act 74, Mich. P.A. 1970

1. Public Land Survey **ECRP #72**

T<u>37N</u> R 6W M-3

READMOND TOWNSHIP

Corner Code #

2. Property Controlling in Section 3. Miscellaneous

Property in Sec.

EMMET

Located In:

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat

5. Private Claims

I, <u>Richard E. Oelke</u>, in a field survey on <u>10 December</u>, 19 <u>99</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,

found as expressed below:

5 15 _ ... 22.. 23. ... 9 10 - in. 29. 28 26 ļ : 11 34 35

NOTE: Not more that 4 comers, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO set corner in 1840's. Trowbridge found ½" rod in 1983. This point has been used in Abstract: subsequent surveys by local surveyors.

See back page for chronological history of corner.

APPROVED LAND CORNER P.A. 345 OF 1990 **Emmet County** RE-CEINE

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found: ½" iron rod, 2' long, set by persons unknown. This point falls +/-6' N of centerline of Division Road and +/-6' E of the centerline of a dirt two track to the south. Fits old fence to the North, +/- 39' S of old N right-of-way fence. Falls in a road cut area.

> 3) N 31° E, 37.21', 5" aspen, tagged w/ a yellow cap in N face

6) N 51° E, 55.35',

3" aspen, tagged 33984 in SE face

2) S42° W, 51.95 pp, tagged 15410 in NW face

4) N 05° W, 33.46', 8" aspen, tagged w/ a yellow cap in SW face

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set: The ½" rod noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program Cap. This position is accepted as a careful and faithful perpetuation of the position of the original corner.

Additional New Witnesses:

N 52° E. 67.99', 6" maple, tagged 33983 in W face S 33° E, 69.41'. N 53° W, 69.90',

10" apple, tagged 33983 in W face 4" aspen, tagged 33983 in E face

RICHARD E **OELKE** ROFESSIONAL SURVEYOR No. 33983

__ Date _____ 10 December 1999

Surveyor's Michigan License No. 33983

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION

LICER A
299

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 72

37-6-M3

T37N R6W cor. bet. SECS. 1,6,7, and 12 DIVISION ROAD and an unnamed road S.

Date	Surveyor	Found	Witnesses		Notes
1840	GLO	Set post	1) NO1°E, 34 2) S25°W, 40		
1968	Green	ECRC work in section 7			
1983	Trowbridge	Survey for Garber, found ½" iron rod			
	<u> </u>	,	1) N11°E,	38.17'	6" poplar
			2) S46°W	51.95	рр
1990	Green	found ½" rod added new witness.			
	,		3) N 38°E,	37.40',	5" aspen
			4) N O1 °W,	33.55',	5" aspen
1997	Hall	found ½" rod			
			2) S48°W	51.88	pp
			3) N 44°E,		4" aspen
			5) N 58°E,	-	4" aspen
			6) NO2°W,	38.47'	7" poplar
			•		• •