MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T	38 N.R. 39 N.R.		də N.	Emmet	COUNTY
DESCRIPTION OF CORNER Sect	ion corne	r common to S	ections 2	-3-3	<u>1-35</u>	
CORNER MONUMENT Left 1 H	pipe in p	lace				
DATE MONUMENT PLACED AND W	ITHESSEDA	p <u>ril 19, 196</u> 2				
WITHESSES TO CORNER	 		····	-		
N _	5"_	Twin Cedar	S 65 E	-	97.91	
1	8#	W. Birch	S 23 W	_	82.11	
CIRCLE CORNER REGISTERED -	ND 16"	Cedar stump	N 5 E		42.81	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found $1^{\#}$ pipe at road intersection E = W = S and in line with fence north. Checks measurement to section corner south. Appears acceptable as section corner.

SURVEYOR'S SEAL

SIGNED Kenneth & Ostling DATE April 24, 1962
REGISTERED KAND SURVEYOR