MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 4 W.

			Em	net	COUNTY
DESCRIPTION OF CORNER Section corn	er common	to Sections	2 - 3-10 -	11	,
CORNER MONUMENT Left 1 1/4" pipe	in place b	elow surface	3	· · · · · · · · · · · · · · · · · · ·	
DATE MONUMENT PLACED AND WITNESSED	lay 22, 196	2			
WITHESSES TO CORNER				·	
N	O' Aspen	s 49 W	71.51		
<u></u>	6" Maple	N 24 W	132.41		<u> </u>
CIRCLE CORNER REGISTERED	•				

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found a 3/4^m iron bolt set in 1/4^m pipe at corner, in centerline of N = S road and in line with trail road east. Considered acceptable as proper location for corner.

SURVEYOR'S SEAL

SIGNED Levels Solling DATE May 29, 1962

REGISTERED LAND SURVEYOR