MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORMER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a survey in this area. Set corner by single proportionate measurement, after determining the theoretical location of the NE corner of Section 31 which falls in lake. The NE corner of Section 31 was fixed at the calculated intersection of the north and east lines of Section 31, said lines being based on mean bearings between section lines 1 mile each way therefrom.

SURVEYOR'S SEAL

SIGNED Coult Delling DATE May 23, 1961