## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 38 N.R. 5W

			E	mmet		COUNTY
DESCRIPTION OF CORNER	1/4 Corner com	mon to se	ections 32 and	33.		
CORNER MONUMENT	l" pipe with 4	h brass	рар			
DATE MONUMENT PLACED AND	WITHESSED May 1	8, 1961				<u></u>
WITHESSES TO CORNER			· <u>·</u>			<u> </u>
	8º Cedar	<b>-</b>	S39W		<u>119</u> .	Links
32	10" Cedar	-	S42E	-	66	links
CIRCLE CORNER REGISTERED	AND			<u></u>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Restored by proportionate measurement, midpoint on line between section corners, by Forestry Division survey crew while making a survey in this area. Unable to identify government BTS, but this point checks cutting lines and appears conformable to subdivision of section 33.

SURVEYOR'S SEAL

SIGNED SECULLE SURVEYOR DATE May 23, 1961