

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 5W


Emmet COUNTY

DESCRIPTION OF CORNER 1/4 Corner common to Sections 28 and 29.

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED May 18, 1961

WITNESSES TO CORNER.....



8" H. Maple - N26W - 143½ links

7" Balsam - S85W - 136½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Reestablished by Forestry Division survey crew while making a survey in this area. Set this corner at fence intersection east and south. This point falls at midpoint on line between restored section corners north and south, and appears to have been acceptable in the subdivision of section 28. Nothing left for government BTs.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE May 23, 1961
REGISTERED LAND SURVEYOR