## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. \_\_38\_\_\_\_ N.R. \_\_5n

			Emmet		COUNTY
DESCRIPTION OF CORNER	Section corner	common to	sections 2	0, 21, 2	8, and 29.
CORNER MONUMENT	1" pipe with 4	" brass cap	, below su	rface.	
DATE MONUMENT PLACED AND I	ITMESSEDAP	ril 28, 196	i		
WITHESSES TO CORNER	5# Elm		563W		76 links
N	5" H.Maple	tra .	N2 <b>74</b>		108 links
+	Fence corn	e <b>r -</b>	East	pre	53 links
CIRCLE CORNER REGISTERED	LND			· · · · · · · · · · · · · · · · · · ·	

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established at apparent centerline intersection of roads N - S and W and in line with fence east. Checks midway between N-S fence lines and was considered best available evidence. Section 21 appears to have been subdivided on basis of this position.

SURVEYOR'S SEAL

SIGNED LEWEL SURVEYOR DATE May 25, 1961