MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 6W

				Emmet		
DESCRIPTION OF CORNER _	Section Corner Co	ommon to	Sections 23,	24, 25, a	nd 26.	
CORNER MONUMENT	l' pipe with 4" b	rass cap	•			
DATE MONUMENT PLACED AND	WITHESSED _April 6	5, 1961				
WITHESSES TO CORNER	•					
N	8 ^m R. Oak	-	n61m	po po	22 links	
25	8 R. Oak		S72E	#	2 <u>1 1/4 links</u>	
CIRCLE CORNER REGISTERED	AND					

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew. Restored this corner on line, and equidistant over original 1/4 and section corners east. Corner falls on east slope of very large sand dune. Suspect that government BT stump may be covered. Cannot double proportion since no good meander corners are available north and west.

SURVEYOR'S SEAL

SIGNED Level JOElling DATE May 25, 1961

REGISTERED LAND SURVEYOR