MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 39 N.R. 4 W.

						Enmet					COUNTY
DESCRIPTION OF CORNER Meand	ier corner	common	to	Sect	tions	23 -	26 on	west	side	of	lake
CORNER MONUMENT Set 1" pi	ipe with 4	alumi	num	cap							
DATE MONUMENT PLACED AND WIT	MESSED <u>May</u>	8, 196	4								
WITHESSES TO CORNER											
_		20" R	. Pi	ne	n 6	4 W	7	0.41			
		8 R	. Pi	ne	N	1 W	8	3.0			
CIRCLE CORNER REGISTERED	•										

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set while making a survey in this township. Set corner on line between section corners at the west shore of French Farm Lake. Area all disturbed by filling, and used as access point, so all previous evidence destroyed.

SURVEYOR'S SEAL

SIGNED Muell Surveyor #19068 DATE June 26, 1964