Remonumentation corner under P.A. 345, Michigan P.A. of 1990

		LAND CORNER RECORD	ATION CENTIFICATE		
For	corners SECTIC	N Filing Requirement of Ac	et 74, Mich. P.A. 1970	DEED 2562 PAGE	125
	Genesee	Located In: Corner	Code ##	FIDER A O O STAGE	* 00
	(County)	Fenton Township			
1	Public Land Surve	דומים ואיים ד	'-3	mo L	AL.
		· 			2
					8
		·			THEORDED
2.	Property Controlling			1800 = 3	a
_	in Section				<u> </u>
3.	Miscellaneous Property in Sec.	S T R S T R	Regi	ster of Deeds Stamp & File N	umber
	Froperty in Sec.	<u> </u>	(1.00 Filedox Res	Ed
4.	Lot No	, Recorded Plat		ABCDEFGH	JKLM
5.	Private Claims				ŤŤŤ
		5.4		2 6 5 4 3	-2-1-1-1
		5 9		4 7 0 10	
,	James E. Kovas, F	PS, PE in a field survey on September 27	19 94	5	-11
ı, _ do	hereby certify that unc	der requirements of P.A. 74, Michigan P.A. of 1970, the co			
in l	ines 1 and 2 above w	vere in conformance with regulations and rules theref	ore as required in the	7 18 17 16 15	13-1
CUI Ma	rent manual of survey nagement or by a decr	instructions of the United States Department of the In ee of a Court of Law and/or that the corner points menti-	iterior, Bureau of Land oned in lines 3, 4 and 5		
abo	ove were in conforman	ce with the rules of the Michigan Board of Land Survey	ors or by a Decree of a	9 19 20 21 22	23 24
		ned, re-established, monumented, re-monumented,	recovered, found as	10	
	oressed below:	n 4 corners, all in the same town and range, ma	w he recorded	10 30 29 28 27	25
NC	on this certifi		ly be recorded	12 31 32 33 34	35 36
				13	
A.	Description of orig	ginal monument and accessories and/or subsequ			
1823/GLO - J. Fletcher, DS, set post, two accessories 1989/Survey - Found 1/2" Re-Rod, Su 1847/RODeeds - No monument description, County Surveyor Post Surveying, three accessories					erstone
	1847/RODeeds - No Witness Book, t	monument description, County Surveyor Post		ssories 'Re-Rod, L.C.R.C., D.L. 2381 P.11,	Gilbert
	1973/RODeeds - No 1	nonument description, Recorded survey D.L. 1847	G. Bonno, RLS #3233	2, three accessories	_
	P. 219, Hammor accessories	nd Engineering, D.W. Hammond, RLS #8890, three		Ratified by Peer	Group i
		and Re-Rod, Recorded survey D.L. 2154 P. 830,		accordance with P.A	k. 345, Tas
	CHMP, A.F. Mi	ller, RLS #12024, four accessories		Co. Rep. Call	a lan
					G CALL
				Date Dect	
В.	Description of cor	ner evidence found and/or method applied in re	storing or reestablishing	corner:	
	ŕ				
	1994/REMON. S	UMMARY OF EXISTING ACCESSORIES		MEASURED	
	1994/Remon Fo	ound 1/2" Re-Rod, Wade-Trim, Inc. Remonumentation,	F3 to G3	2644.17'	
		45W 38.60' tag in 18" tree (now 32")	(measured to in-grow		
		30E 64.53' tag in 20" tree (now 28") AST 55.35' tag in 20" tree (now 24")		64.87′ 55.39′	
	1983/RODeeds W	est 33.75' fence post	(measured to tag)	33.84′	
		25E 64.45′ 25″ Cotton (new 28″) 45W 38.5′ 26″ Oak (new 32″)	(measured to tag) (measured to tag)	64.87′ 38.50′	
		45W 38.5' 26" Oak (now 32") 25E 64.86 22" Ash (now 28")	(measured to tag)	64.87	
	•		•		
	Ratified by Genesee	County Peer Group, December 7, 1994.			
	Mathica by deficient	Course tour Group, Boomson 1, 10011			
				1	
C.	Description of mo	nument for corner and accessories established	to perpetuate locating the	e position of the corner:	
				OF MIC	A STATE OF THE STA
	ACCESSORIES: N60W 38.50' to	Nail/G. Bonno tag in NE face of 32" Oak	I set the standard 30	"X2 3/8" Bernts in stainless steel	HIJGO TO
	N25E 64.87' to	Nail/G. Bonno tag in 28" Ash	with brass remonume		1
		Nail/G. Bonno tag in Fence Bost		2 * / E.;	1 * 1
	East 55.39' to	Nail/blank tag in 24″ Oak		KOVAS	***
			The second of th	SURVEYOR	Į Į
				33138	133
			1 And	S	CUL
				SPED LAN	O James
	ι	2777		· · ·	9.4.
٠.	\ ,	11100	Date 12/	6/94	
	gned by	V) TO TO	Date	· / · · ·	
Su	ryeyor's Michigan L	icense No3313 7	FORM APPRO	VED BY MICHIGAN STATE BOARD OF LAND SURVE	
REVISED MAY 14, 1979 REVISED JAN., 1983					

Alli