

**SURVEY &  
REMONUMENTATION**

1995 RE-MONUMENTATION PROGRAM

MAY 31 2000

MASTER LIBER 3276 PAGE 431

**SECTION  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>GENESEE</u> (County)	Located in:	Corner Code: //
1. Public Land Survey	T <u>6N</u> R <u>6E</u>	<u>A-5</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECORDED  
APR 4 2 55 PM '95  
REGISTERED  
9.00 Filed & Recd  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, RICHARD H. KRAFT, in a field survey on, DECEMBER, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1823 - GLO - HARVEY PARKE, DEPUTY SURVEYOR, SET CORNER - NO ACCESSORIES
  - 1885 - F.W. PETTER, CO. SURVEYOR - FOUND STAKE & STONES - SET 1 ACCESSORY  
GCRC - FOUND IRON PIPE - SET 5 ACCESSORIES
  - 1978 - A.F. MILLER - FOUND PIPE - RECORDED 3 ACCESSORIES
  - 1988 - M. VANRAEDONCK - FOUND 3/4" PIPE - RECORDED 4 ACCESSORIES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

199 GENESEE COUNTY REMONUMENTATION PROGRAM

- 1978 - FOUND ONE ACCESSORY
- 1988 - FOUND 2 ACCESSORIES
- 1995 - FOUND 3/4" PIPE IN MONUMENT BOX

Ratified by Peer Group in  
accordance with P.A. 345, 1990  
Co. Rep. Carl Carlson  
Date 12-20-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET GENESEE COUNTY MONUMENTS IN MONUMENT BOX
- NAIL & RAG IN POWER POLE S 20° E, 25.0 FT.
  - IRON - S 55° E, 46.4 FT.
  - GC TAG IN 8" TREE; S 60° E, 52.35 FT.
  - NAIL & TAG IN POWER POLE, N 60° W, 60.95 FT.

20108

Signed by Richard H Kraft Date 12-22-95  
Surveyor's Michigan License No. 10064

77