

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>GENESEE</u> <small>(County)</small>	Located In:	Corner Code = <u>11</u>
1. Public Land Survey	T <u>6N</u> R <u>6E</u>	<u>G-4</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECORDED  
APR 11 2 56 PM '95  
20116  
9.00  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, RICHARD H. KRAFT, in a field survey on, DECEMBER, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1823 GLO-HARVEY PARKE - SET CORNER - NO ACCESSORIES
- 1920 - GENESEE COUNTY ROAD COMMISSION - FOUND IRON PIN - 4 ACCESSORIES
- 1972 - A.V. KUPISCH - FOUND 1" SQUARE BAR - 6 ACCESSORIES
- 1995 - RICHARD H. KRAFT - FOUND 1" SQUARE IRON

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1995 GENESEE COUNTY REMONUMENTATION PROGRAM
- 1970'S - FOUND TWO ACCESSORIES
- 1972 - FOUND ONE GENESEE COUNTY ROAD COMMISSION ACCESSORY
- 1995 - FOUND TWO KUPISCH ACCESSORIES

Ratified by Peer Group in accordance with P.A. 345, 1990

Co. Rep. Carl Carlson  
Date 12-20-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET STANDARD GENESEE COUNTY MONUMENT IN MONUMENT BOX
- GAS PIPE MARKER, S35°W, 70.4' FT.
- GAS PIPE MARKER, S35°E, 77.2' FT.
- GC TAG IN POWER POLE, N15°E, 58.4' FT.
- NAIL & TAG IN POWER POLE, N20°E, 37.11 FT.

SURVEY & REMONUMENTATION

MAY 31 2000

SECTION

Signed by Richard H. Kraft Date 12-23-95  
Surveyor's Michigan License No. 10064