

RECORDED  
RECORDED  
APR 11 2 56 PM '95  
GENESEE COUNTY

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>GENESEE</u> (County)	Located in:	Corner Code #/1
1. Public Land Survey	T <u>6N</u> R <u>6E</u>	<u>M-4</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling In Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

20124

9.00 Filled + Recd

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, RICHARD H. KRAFT, in a field survey on, DECEMBER, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	1	2	3	4	5	6	7	8	9	10	11	12	13
3	14	15	16	17	18	19	20	21	22	23	24	25	26
4	27	28	29	30	31	32	33	34	35	36	37	38	39
5	40	41	42	43	44	45	46	47	48	49	50	51	52
6	53	54	55	56	57	58	59	60	61	62	63	64	65
7	66	67	68	69	70	71	72	73	74	75	76	77	78
8	79	80	81	82	83	84	85	86	87	88	89	90	91
9	92	93	94	95	96	97	98	99	100	101	102	103	104
10	105	106	107	108	109	110	111	112	113	114	115	116	117
11	118	119	120	121	122	123	124	125	126	127	128	129	130
12	131	132	133	134	135	136	137	138	139	140	141	142	143
13	144	145	146	147	148	149	150	151	152	153	154	155	156

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1823 - GLO - HARVEY PARKE - DEPUTY SURVEYOR - SET CORNER - NO ACCESSORIES
- 1920 - GCRC - FOUND STAKE - 4 ACCESSORIES
- 1956 - PLAT RECORDED - 1 ACCESSORY
- 1970 - GCRC - SET MONUMENT BOX - 3 ACCESSORIES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1995 GENESEE COUNTY RE-MONUMENTATION PROGRAM
- 1920 - GCRC - ONE ACCESSORY
- 1956 - PLAT RECORDED - ONE ACCESSORY
- 1970 - GCRC - ONE ACCESSORY
- 1995 - E 1/4, SECTION 12 IS 76.0 FT. NORTH OF W 1/4, SECTION 7, T6N, R7E

Ratified by Peer Group in accordance with P.A. 345, 1990  
Co. Rep. Carl Carlson  
Date 12-27-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET STANDARD GENESEE COUNTY MONUMENT IN MONUMENT BOX
- FOUND NAIL & TAG IN POWER POLE - N 85° E, 40.59 FT.
- SET GC TAG IN 6" TREE - N 40° W, 118.45 FT.
- SET GC TAG IN POWER POLE - S 30° E, 85.38 FT.
- W 1/4 CORNER, SECTION 7, T6N, R7E, - SOUTH 76.0 FT.

SURVEY & REMONUMENTATION

MAY 31 2000

SECTION

Signed by Richard H Kraft  
Surveyor's Michigan License No. 10064

Date 12-29-95