

MAR 23 2000

SECTION

MANUEL 4355 PAGE 119

1999 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Located In: Grand Corner Code # Genesee Blanc (County) D-13 T6N R7E 1. Public Land Survey R R R 2. Property Controlling R in Section 3. Miscellaneous Property in Sec. _ , Recorded Plat 4. Lot No. 5. Private Claims I, Kevin B. Cleaver, in a field survey on December 9, 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: General Land Office (GLO) field notes: set post w/two accessories Cornerstone Surveying and Engineering witness ties: rail road spike Undated w/one accessory Land Corner Recordation Certificate (LCRC), Liber 1838, Page 153: rail road spike w/two accessories P.A. 132 Certificate Survey, Liber 1840, Pages 638-639: rail road spike w/ two accessories and half-mile 8/29/72 8/29/72 measurement Wade-Trim, Inc. field notes: closing corner measurement and measurement to section corner 1999 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: GLO corner and accessories not found Recovered corner and one accessory from undated witness ties Recovered corner from 1972 LCRC Recovered corner and confirmed within acceptable tolerance half-mile measurement from 1972 certified survey Confirmed closing corner measurement and measurement to section corner from 1999 field notes This monument found was ratified by the Genesee County Remonumention Peer Review Committee on December 1, 1999. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set in concrete the standard Bernsten monument SS-A-5BR-30 with 3 1/4" brass cap stamped "Genesee County Remonumention Corner, 1999, #29242" over rail road spike at the base of a 9" diameter concrete post. Ratified by Peer Group in N 80° W 102.00' set Genesee County witness tag in south face of 30" oak accordance with P.A. 345, 1990 34.91' set Genesee County witness tag in northeast face 18" shagbark hickory Co. Rep. Du N 31° W 43.19' set Genesee County witness tag in west face of 4" ash Date 12-1 North 91.59' set Genesee County witness tag in northwest face of 7" ash N 25° E 5.05' Rowe Inc. Trav. rod S 89° E Date ___ Signed by Levin Bankley Surveyor's Michigan License No. PAHRELD CLEAVER FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 193 **PROFESSIONAL** REVISED MAY 14,197 REVISED JAN., 198 SURVEYOR REVISED OCT., 189

No.

29242

POFESSY

99-GCRM-GR-3395