

MAR 23 2000

SECTION

1999 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

MASSER 4355 PAGE

	Filing Requirement of Act 74, Mich. P.A.	1970
For corners in		Dec 2
Genesee	Located In: Grand Corner Code #	
(County)	Blanc	
1. Public Land Survey	T <u>6N R7E E-13</u> T R T R	109685
2. Property Controlling S	T R T R T R T R T R T R T R T R T R T R	Ale G. Ø Register of Deeds Stamp & File Number
4. Lot No, Recorded P 5. Private Claims	at	A B C D E F G H I J K L
under requirements of P.A. 74, Michigan and 2 above were in conformance with current manual of survey instructions of of Land Management or by a decree mentioned in lines 3, 4 and 5 above w	rey on December 8, 19 99, do hereby state that P.A. of 1970, the corner points mentioned in lines 1 regulations and rules therefore as required in the he United States Department of the Interior, Bureau of a Court of Law and /or that the corner points ere in conformance with the rules of the Michigan ee of a Court of Law; established, re-established, ssed below:	2
NOTE: Not more than 2 corners, on this certificate.	all in the same town and range, may be recorded	10 - 30 - 29 - 28 - 27 - 26 - 25 - 11
A. Description of original monumer	t and accessories and/or subsequent restoration:	12 - 31 - 32 - 33 - 34 - 35 - 36
1823 GLO field notes: Undated Cornerstone Surve 3/8/73 Gould Engineering 4/2/79 P.A. 132 Certified to section corner	ce (GLO) field notes: set post w/two accessories measurement to closing corner sying and Engineering survey: pipe w/four accessories g, Inc. (GEI) records: pipe w/three accessories Survey, Unrecorded: pipe w/two accessories, closing co	
10/1/92 P.A. 132 Certified	Survey, Liber 2462, Page 476: re-rod w/four accessorie Survey, Unrecorded: pipe and closing corner measuremotes: closing corner measurement	
B. Description of corner evidence to	ound and/or method applied in restoring or reestablishing	g corner:
Recovered corner and four acce Recovered corner and three acc Recovered corner, one accessor survey Recovered corner, three accessor survey	erance 1823 closing corner measurement ssories from undated survey	asurements to section corner from 1992 certified
Confirmed closing corner measurement	rement from 1998 field notes	•
This monument found was ratif	ed by the Genesee County Remonumention Peer Review	Committee on December 1, 1999.
C. Description of monument for co	ner and accessories established to perpetuate locating the	he position of the corner:
Set the standard Bernsten mon	iment SS-A-5BR-30 with 3 1/4" brass cap stamped "Ger	nesee County Remonumention Corner, 1999,

Delta Surveying and Engineering red
2" diameter pipe With Consumers Power cap
Oakland Count frem numers attorned with 2" brass cap. Date 12/20 #ESCHONAL VEYOR Ñο. FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 29242

Ratified

by

accordance with P.

Peer

Group in

A. 345, 1990

N 13° E 32.85' S 28° E 40.02'

S 85° E 22.46'

Surveyor's Michigan License No.

#29242" 6" below surface over 1.2' long 1" diameter pipe

Oakland County

S 30° W 26.15' set Genesee County witness tag in west face 24" twin oak N 31° E 20.44' set Genesee County witness tag in northwest face 24" oak