SURVEY & REMONUMENTATION

MASTER 3685 PAGE

MAR 0 5 1998

DEC 29 11 32 AM '97

ENESSEE COUNTY

Ratified by Peer

accordance with P.A. 345, 1990

L

Group in

SECTION 1997 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in | | |
|---|-------------------|---------------|
| Genesee (County) | Located In: | Corner Code # |
| 1. Public Land Survey | T_6N_R_7E_ TR | K-3 |
| Property Controlling in Section Miscellaneous Property in Sec. | STR STR STR | |

4. Lot No. , Recorded Plat 5. Private Claims I, <u>Kevin B. Cleaver</u>, in a field survey on <u>October 30</u>, 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey

instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, reestablished, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Set post and two (2) accessories GCRD Recorded plat of "Sun Valley Subdivision" L 26, P 55 1823 Dec. 23, 1954 Jan. 19, 1956 GCRD Recorded Plat of Schumacher Terrace" L 29 P 28 Jan. 1967 **CPCo** Feb. 18, 1981

GCRD LCRC, L 2126 P 372 - Set Tag, five (5) accessories GCRD LCRC, L 2379 P 317 - Found Nail/Tag in Pavement, five (5) accessories Dec. 12, 1989

March 22, 1990 GCRD Certified Survey, L 2387 P 904 and 905 - Found Nail/Tag in Pavement, three (3) accessories GCRD Certified Survey, L 2524 P 61 and 62 - Found Nail/Tag in Pavement, three (3) accessories Jan. 27, 1994 March 26, 1997 GEI Found Nail/Tag in Asphalt, four (4) accessories

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Nail and Tag in pavement

Found distances K-3 to SW Corner of SE ¼ of SE ¼ and K-3 to SE plat corner and angle SW plat corner, K-3, SE plat corner in the recorded plat of "Sun Valley Subdivision" L 26 P 55 December 23, 1954; Found distance K-3 to NW corner of plat and angle NW corner of plat, K-3, NE corner of plat in the recorded plat of "Schumacher Terrace" L 29 P 28 January 19, 1956; Found distances K-3 to NW corner of NE ¼ of NE ¼, K-3 to J-3 and K-3 to K-4 from January, 1967 C.P.Co. records; Found three (3) accessories from February 18, 1981 LCRC L 2126 P 372; Found three (3) accessories from January 12, 1989 LCRC L 2379 P 317; Found two (2) accessories from March 22, 1990 survey L 2387 P 904 - 905; Found two (2) accessories form January 27, 1994 survey L 2524 P 61 - 62; Found three (3) accessories from March 26, 1997 GEI records.

The monument found was ratified by the Genesee County Peer Review Committee on November 13, 1997, as the accepted corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set the standard Bernsten monument SS-A-5-BR-30 with 3 1/4" brass cap stamped Genesee County Re-monumentation Corner 1997, #29242 in a Monument Box.

N 12° E, 50.83' - Found "X" in the South rim of a sanitary manhole S 10° E, 44.25' - Found nail and tag in the West face of an 8" spruce S 38° W, 74.90' - Found nail and tag in the Northeast face of a power pole N 33° W, 65.18' - Found nail and tag in the Northeast face of a power pole

Signed by Down Dank. Kevin Banfield Cleaver, P.S

BANFIELD CLEAVER PROFESSIONAL SURVEYOR

> No. 29242

OFESSIO

Date 12/24/97

97H-GCRM-LCRC-3644

Field Manager

Surveyor's Michigan License No. 29242

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1976

REVISED JAN., 1983 REVISED OCT., 1995.

88566