SURVEY & ATION

APROT 1995

Filing Requirement of Act 24

| For corners in Chrysonyman many converse   | Act 74, Mich. P.A. 1970, [1] 2 17 PH 194   |
|--|--|
| 1 • P N H N H H  | UNDER P.A. 345, MICHIGAN P.A. OF 1990)   |
| (County)   | DEED 2528 PAGE 808   |
| 1. Public Land Survey T 8N R 6E  | D-3  |
|  | 14748  |
| <del>-</del> -   |  |
| 2. Property Controlling S T R  |  |
| `  | 9.00 Filed & Recd  Register of Deeds Stamp & File Number                                       |
|  | Register of Deeds Stamp & File Number  |
| 4. Lot No, Recorded Plat   |  |
| 5. Private Claims  |  |
| •  | 2 6 5 4 3 7 2 1 1  |
| RICHARD H. KRAFT NOVEMBER 18.  |  |
| i,, in a field survey on   | , 19 93 5  |
| in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the   |  |
| current manual of survey instructions of the United States Department of the Management or by a decree of a Court of Law and/or that the corner points men |  |
| above were in conformance with the rules of the Michigan Board of Land Survi<br>Court of Law; established, re-established, monumented, re-monumented       | eyors or by a Decree of a  |
| expressed below:   | 10 30 29 28 27 26 25   |
| NOTE: Not more than 4 corners, all in the same town and range, n on this certificate.  |  |
| on this certificate.   | 12 31 32 33 34 35 36   |
| A. Description of original monument and accessories and/or subsections.  | quent restoration:   |
| 1822 GLO HORATIO BALL, SET POST  | 1974 CARL CARLSON, FOUND 3/4" IRON BAR<br>LIST 3 ACCESSORIES                                   |
| 1886 J.W. PETTIE, FOUND STONE AND SET IRON STAKE, LIST 2 ACCESSORIES   | 1974 K. PIOTROWSKI, FOUND MONUMENT BOX<br>LIST 3 ACCESSORIES                                   |
| 1954 GCRC - FOUND IRON PIN<br>LIST 7 ACCESSORIES   | 1989 CERTIFIED SURVEY, PAUL BROWN<br>LIST 4 ACCESSORIES  |
|  | 1992 CERTIFIED SURVEY, PAUL BROWN, FOUND 3/4" ROD IN MON. BOX. LIST 4 ACCESSORIES              |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:   |  |
| 1993 GENESEE COUNTY REMON. PROGRAM   | I CONCLUDE THAT THE CORNER HAS LONG BEEN   |
| RECOVERED 1" IRON ROD IN MON. BOX 3 ACCESSORIES FORM CERTIFIED   | PERPETUATED AND DOESN'T SEEM TO HAVE CHANGED. THE RECOVERED ACCESSORIES SHOW IT IS IN THE SAME |
| SURVEY, 1992   | POSITION. I ACCEPT IT AS A FATTHFUL AND CAREFUL  |
|  | RESTORATION OF TEH POSITION OF THE ORIGINAL CORN   |
|  | APPROVED BY GENESEE COUNTY PEER REVIEW GROUP,  |
| •  | DEVEMBER 7, 1993   |
|  |  |
|  | •  |
|  |  |
| C. Description of monument for corner and accessories established  | to perpetuate locating the position of the corner:   |
| ACCESSORIES:   | I SET THE STANDARD BERNSTEN MONUMENT (3 1/4"   |
| NORTH, 51.90' FOUND NAIL AND TAG IN POWER POLE   | D. BRASS CAP STAMPED - "GENESEE COUNTY   |
| SOUTH, 44.40' FOUND NAIL AND TAG IN POWER POLE S10°W, 44.40' FOUND NAIL AND TAG IN 10" OAK   |  |
| S45°W, 57.22' SET NAIL/G.C. REMON.TAG IN 20" TWIN ELM  | O.D. STAINLESS STEEL TUBE) OVER IRON ROD IN MONUMENT BOX.                                      |
| N50°E, 76.95' SET NAIL/G.C. REMON.TAG IN 4" CEDAR  |  |
| <b>,</b>   |  |
| Alice OHlland.   | 1/1/10/10/10   |
| Signed by / [ www.] + flage  | Date NN,19,1993  |
| Surveyor's Michigan License No. 10064.   | FORM APPROVED BY MICHIGAN STATE GOARD OF LAND SURVEYORS, JAN. 28, 1971                         |
|  | REVISED MAY 14, 1975   |