MAR 23 2000

1999 GENESEE COUNTY REMONUMENTATION PROGRAM 😁

2110 00 0	LAND CORNER RECORDATION CERTIFIC	
SECTION	Filing Requirement of Act 74, Mich. P.A.	1910
For corners in		
Genesee (County)	Located In: Richfield Corner Code #	6 6 8
1. Public Land Survey	T8N R8E G-7	
1. Public Land Survey	T R	STE E ROOM
•	TR	0,
2. Property Controlling	TR	a lad & All OUN
in Section	S TR	Thua your 7.00
3. Miscellaneous	STR	Register/of Deeds Stamp & File Number
Property in Sec.		
4. Lot No, Recorde	d Plat	ABCDEFGHI _{JK} L
5. Private Claims		1 2 6 5 4 3 2 1
I, Kevin B. Cleaver, in a field	survey on November 30, 19 99, do hereby state	3
that under requirements of P.A. 74,	Michigan P.A. of 1970, the corner points mentioned in nance with regulations and rules therefore as required in	4 - 7 - 8 - 9 - 10 - 11 - 12
the current manual of survey instru	ictions of the United States Department of the Interior,	5
mentioned in lines 3, 4 and 5 above	a decree of a Court of Law and for that the corner points we were in conformance with the rules of the Michigan	7
Board of Land Surveyors or by a limonumented, recovered, found as e	Decree of a Court of Law; established, re-established,	8 _ 19 _ 2021 _ 2223 24
,		9
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range, may be recorded	10302928272525
		12-31-32-33-34-35-36
A. Description of original monu	ment and accessories and/or subsequent restoration:	13
	office (GLO) fieldnotes: set post w/two accessories. y Road Commission (GCRC) records: half-mile measurement.	
4/22/1913 GCRC plans: m	neasurements to section corner.	
7/12/1948 Gould Engineer measurement.	ing, Inc. (GEI) survey: measurements to section corner and half-mile	·
4/29/1960 GCRC State Hig 3/23/1973 Land Corner Re	ghway Plans: pipe w/four accessories. cordation Certificate (LCRC), Liber 1875, Page 550: monument box	w/four accessories.
5/7/1976 Rowe Incorpora	ated Records; wood hub in monument box wifour accessories. Ed Survey, Liber 2434, Pages 100-101; rod in monument box wifive a	
6/9/1992 GEI records: m	easurements to section corner and half-mile measurement.	•
	ed Survey, Liber 3834, Pages 432-433: iron in monument box w/four a d in monument box w/four accessories.	accessories and measurement to section corner.
B. Description of corner evider	nce found and/or method applied in restoring or reestablishing	g corner:
GLO corner and accessories no		
Confirmed within acceptable to Unable to confirm 4/22/1913 G	lerance 1910 Genesee County Road Commission half-mile measurer CRC measurement.	ment.
	ection corner and half-mile angle measurement from 1948 GEI survey accessories from 1960 GCRC plans.	<i>f</i> .
Recovered corner and one acc Recovered corner from 1976 R	essory from 1973 LCRC.	
Recovered corner and four acc	essories from 1991 certified survey.	4000 CEL ********
Recovered corner, four access	lerance half-mile distance and measurements to section corner from ories, and confirmed measurement to section corner from 1998 certifi	ied survey.
	essories from 1999 GEI survey. fied by the Genesee County Remonumentation Peer Review Committ	tee on November 24, 1999
	or corner and accessories established to perpetuate locating t	,
•	ernsten monument SS-A-5BR-30 with 3 1/4" brass cap stamped "Ger	
over rod in monument box.	Sind in item and the second se	in the second se
	l tag in southeast face power pole County witness tag in southwest face power pole	i .
N 50° E 54.52' found Gould E	ingineering, Inc. nail and tag in southeast face power pole	
N 80° E 123.58' found Gould ا	Engineering, Inc. nail and tag in southwest face power pole	1 60
Signed by Seven /	Benfull Velstown Date	12/20/99
Surveyor's Michigan License No	KEVAN	•
		HIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1' by Poor Group in REVISED MAY 14,1' REVISED JAN. 12

99-GCRM-GR-3374

SURVEYOR No.

accordance with P.A. 345, 1990 REVISED OCT., 1995

Co. Rep. 🥚 11-24-99 Date _