## GLADWIN COUNTY REMONUMENTATION

UBER 001 PAGE 198

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970.

For corners in	rining r	reduitement of Act	/4, MICH. F	7.A. 19/U	\$	TATE OF MICHIGAN GLADNIN COUNTY
GLADWIN	Located In:	Corner Code #			÷.	FILED - Remonumentation
(County)					17	OCT 97 1:24 P.H.
1. Public Land Survey	T 17N R 1E	K-6	=			-
•	TR TR		-			BONNIE K. HOUSE REGISTER OF DEEDS
	TR		•			WEGIGIEN OF DEEDS
2. Property Controlling in Section	S TR	_	-	.ශ්		
3. Miscellaneous	S TR		• •			
Property in Sec.	S TR	-	- 		Register of	Deeds Stamp & File Number
•						Doods Clarify at 110 (Mariber
4. Lot No, Recorde 5. Private Claims				,	BCD	EFGHIJKLM
J. Filvate Cialitis			× ·	1 2		
				3		
MARK R. ROBISON	in a field survey on Mar	ch 25 , 19 97 do h	ereby state that	tunder 4		9-10-11-12
requirements of P.A. 74, Michigan I conformance with regulations and rule	les therefore as required in t	the current manual of sur	vev instructions	enfthe 5		
United States Department of the Inte that the corner points mentioned in	rior, Bureau of Land Manac	tement or by a decree of a	Court of Law:	and for a	1 <mark>81</mark> 7	16 15 14 13
Board of Land Surveyors or by a recovered, found as expressed below	Decree of a Court of Lar	w; established, re-estab	lished, monum	nented,		
-				**** <b>8</b>	1'92'0 	21 22 23 24
NOTE: Not more than 2 corners on this certificate.	s, all in the same town an	d range, may be record	<b>jed</b>	9		
OH uns ceruncare.				10	—30— —29 	28 27 26 25
	•			11	1   1	32 34 25 36
			a de la	12		33 34 35 36
A. Description of original monu	ment and accessories a	nd/or subsequent rest	toration:		473.00	
1831 Henry Parke Set Post	Found	Lapham survey d 1/4" iron			APPRO	OVED LAND CORNER
Wit(1)N39E 30 links 28" Pine (2)S42W 11 links 24" Pine		3)West Conc. Mon 33. S25W 8" Oak 51.40'	.00"	r		P.A. 345 of 1990 Gladwin County
	(5)	N50E 20" W. Pine 41.	90'		1 6 2	<i>/</i> /
1964 Lapham survey	1995	Lapham survey		Co. Pe	P.X.	Alyen
	Wits	ame as (3),(4)&(5)		.∵Date <u>\</u>	-9/6	8/47
	1968	Plat of Arapahoe Trail	\$		,	
B. Description of corner evider	nce found and/or method	d applied in restoring o	or reestablishi	ing comer:		
No corner found. Set corner is				_	& (5).	
					(1)	
						·
See dossier for detailed report					• •	
ess according for accepted report	•			ika ili Ne		
				100 mg		
	•	\$ 1 to 1			in a en	
		• • •				
C. Description of monument for	corner and accessories	established to perpet	uate locating	the position		or: SURVEY &
K-6: Corner common to Section			3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3			NUMENTATION
Set 5/8" x 36" rerod with Glady	vin County Re-mon Cap	marked P.S.#2/458	n Monument	Box,		
Witnesses:	Pi				J	ian 0 8 1998
N50E 20" Pine, nail & tag, 41.9 West, Concrete Monument, 33.			***			
S45W 10" Oak, nail & tag, 51.3	5'				4	SECTION
N15W 12" Pine, nail & tag, 44.0	100	E OF MICH		<u> </u>		
11	00 850	MARK R				
Signed by / Aug	(1.63 H=4	ROBISON *	Date	10	クーク・マ	ages of
Surveyor's Michigan License No.	27458 P	SURVEYOR >	T Daile	,		
, <u> </u>	H.	No.	Ţ			
	As'	. 27458	M APPROVED P	Y MICHIELAN STA	TE BOARD OF D	ROFESSIONAL SURVEYORS, JAN. 28, 1971
	WEEK.	PESSIONA	FROTED B		・ことのないので	ROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983
		The state of the s				REVISED OCT., 1905
						•