

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY


T 17 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 32-33 on S Bdry of Twp.

CORNER MONUMENT Set Department Monument

DATE MONUMENT PLACED AND WITNESSED 5-12-71

WITNESSES TO CORNER.....



5" S. Maple N 45 E 24.0'

6" S. Maple N 70 W 24.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey of Section 32. Found old post at corner, previously located in 1930s survey, apparently restored from U.S.B.T. sites according to CCC survey record.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Timothy J. Ostling
REGISTERED LAND SURVEYOR

DATE

5-19-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68