

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


GLADWIN COUNTY
T 17 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 28-29-32-33

CORNER MONUMENT Set Dept. Mon. below road surface

DATE MONUMENT PLACED AND WITNESSED 5-12-71

WITNESSES TO CORNER.....



Nail in Power pole N 49 E 87.2'

Nail in Fence post S 3 W 34.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored in road intersection 33' North of fence corner in line with roads N-E & W. Any previous corner apparently destroyed in road construction. Fits well for line and distance to corners or road intersection North, East and West.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Penwith Postling
REGISTERED LAND SURVEYOR

DATE

5-19-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68