SURVEY & REMONUMENTATION

DEC 0 1 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Gladwin County Remonumentation

LIBER .001 PAGE 282

SECTION			THEE COL
For Corners in			
GLADWIN		1	
(County) Loca	ted In: Co	rner Code#:	
		•	STATE OF MICHIGAN
1. Public Land Survey T18	N R. 02W	K-10	GLADUIN COUNTY
	R		FILED-RENOWUHENTATION
	_		
			19 NOV 1999 2:04:16 PN
<u> </u>			•
	h		BONNIE K. HOUSE
Property in Section S T			REGISTER OF DEEDS
4. Lot No, Recorded I	Plat		Register of Deeds Stamp & File Number
5. Private Claims			Anglister of Deeds Stamp & The Number
I. Mark R. Robison, in a field survey on April	1998, do hereb	y certify that under	1ABCDEFGHIJKLM
requirements of P.A. 74, Michigan P.A. of 1970, the	e comer points mentione	d in lines 1 and 2 above	2 6 6 4 2 2 1 2 1
were in conformance with regulations and rules ther instructions of the United States Department of the	etore as required in the dinterior. Bureau of Land	Surrent manual of survey Management or by a	3 4 3 4 3 7 2 1 1
decree of a Court of Law and/or that the corner point	its mentioned in lines 3.	4 and 5 above were in	4-7-8-9-10-11-12-
conformance with the rules of the Michigan Board of	of Land Surveyors or by	a Decree of a Court of	5
Law, established, re-established, monumented, re-m	onumented, recovered, t	ound as expressed below.	6-18-17-16-15-14-13-
NOTE: Note: 1		•	7
NOTE: Not more than 2 corners, all in	the same town and	range, may be	8 19 + 20 + 21 + 22 + 23 + 24 -
recorded on this certificate.			9-+
			10-30+29+28+27+26+25-
			12-21-22-22-22-24
A. Description of original monument	and accessories ar	d/or subsequent	12-31-32-33-34-35-36-
restoration:		•	
1856 Geo H. Cannon		pham 4 surveys	*
Set Post Old 1/4 Cor	Found	P.K. Nail & Tag	
Wit-(1)Y. Birch 10 N80E 25	Wit-same a	s (3), (4) & (5)	
(2)Hemlock 8 N63W 24	4000 4		•
1070 London I CDC#252 &		T Found P.K. Hole	
1979 Lapham LCRC#252 & survey Set P.K. Nail MPOL	Set P.	K. Nail utilizing with	ess and
Wit-(3)East Cor Post 57,90	surv See MDOT	ey data by Lapham Plans#26011 for Loc	0. 11/14
(4)N70W P.P. 73.15	Sec IVIDO1		or with
(5)S45E Fe. Post 73.35	1998 Lapha	m m	
(Note-above not correctCorrect set at		nce K-11 - K-10 = 26	33.69
prorated gov't distance)		nce K-10 - K-9 = 264	
			·
B. Description of corner evidence four	id and/or method a	applied in restoring	or re-establishing corner:
			APPROVED LAND CORNER
Found P.K. Nail set by MDOT in Northbor	und lane 5 feet+/- E	ast of centerline.	P.A. 345 of 1990
Nail agrees with witnesses (3) & (5). Also	agrees with Laphar	n 1979, 1980 &	Gladwin County
1998 measurements to K-9 and K-11.			Chadwin County
			Co. Rep. 1 Many
See dossier for detailed report.			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
ove dosorer for detailed toport.			Date 10/30/98
			. / /
C. Description of monument for corner	and accessories	established to nernet	tuate locating the position of the corner:
K-10: 1/4 Corner common to Sections 25 &	& 26. Set 5/8" x 18	rerod in Monument	Box with Gladwin County Remonumentation cap m
P.S.#27458.			y
Witnesses:			Monte
East Corner Post, nail & tag, 57.90'			TE OF MICH,
vva nan W WE J.70			AF AT

East Corner Post, nail & tag, 57.90' S45°E Fence Post, nail & tag, 73.25'

West 1/2" Rerod 70.50'

N70°W Gate Post, nail & tag, 67.70' (MDOT)

S45°W ½" Rerod 84.10' (witness only) N55°W ½" Rerod 83.35' (witness only)

Surveyor's Michigan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.22, 1971
REVISED MAY 14, 1975
REVISED JAN., 1913
REVISED OCT., 1995

MARK R.

ROBISON

ROFESSIONAL

SURVEYOR No.