LAND CORNER RECORDATION CERTIFICATE

	Filing Requ	uirement of Act 74, Mic	cn. PA 1970
For Corners In: Gladwin (County)	Located In	Corner Code #	
Public Land Survey	T 19N R 2E T R	<u>C1</u>	
2. Property Controlling in Section	S T R R		
Miscellaneous Property in Section			Register of Deeds Stamp & File Number
4 Let No.			
4. Lot No:	Recorded Flat.		A B C D E F G H I J K L M
5. Private Claims: _			2 6 4 5 4 3 2 1
requirements of PA 74, Mi and 2 above were in conforthe current manual of sui Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established	field survey on April 19, 2006 do he chigan PA of 1970, the corner point ormance with regulations and rules the rey instructions of the United Stanagement or by a decree of a Courlines 3, 4 and 5 above were in conformation of Land Surveyors or by a Decree, monumented, recovered, found as a corners, all in the same tower of the course of	ts mentioned in lines 1 therefore as required in tes Department of the t of Law and/or that the formance with the rules e of a Court of Law; expressed below:	3 4
			13
A. Description of original monument and accessories and/or subsequent restoration:			
Set post at interse B. Ash 8" S24°E 3 - CCC Notes – 193 Set random mile p post. South rando - LCRC - #20 – K. record distance W NE Cor. of Hse S6 Mon. N48°E 49.9'	a line 6 L. West of Cor. 31 & 32. action. B. Ash 8" S29°W 34 L. 49 L. – J. Mullett – 1846 0's – West on N. bdy of Sec. 5. bost. Random post is 2:66 S. & 6 bost. Random post is 2:66 S. & 6 bost. Sec. 31 & 32, Test of corner for Sec.	1:47 W. of ¼" pipe at 20N, R2E;	
B. Description of corner	evidence found and/or method	applied in restoring or re-	establishing corner:
C1- Closing corner common to Sec. 5 & 6, T19N, R2E – On 7/28/04 found RR spike in Bit. Rd. at Rec. GLO distance of 3.96' West of 'E13', T20N, R2E. On 4/11/06 found ½" rebar in Mon. Box replacing RR Spike. ½" rebar being 0.15' S. of standard line as monumented to West. Removed ½" x 18" rebar & Mon. Box to check for Ostling 1 ¼" pipe but found nothing else. Thus set 2 ½" Brass Cap on 5/8" x 34" rebar on Standard line at record GLO Distance (3.96') West of 'C13', T20N, R2E as noted by Ostling and 0.15' N. of found RR spike & ½" rebar. 2 ½" Brass Cap accepted as the best available evidence of the position of the original corner.			
C. Description of monu	ment for corner and accessories	established to perpetual	te locating the position of the corner:
·	IR Brass Cap on 5/8" x 34" iron r		
East 3.96' to 'C13 N39°W 44.08' to ' N26°W 65.41' to ' N39°E 82.51' to s S54°E 59.70' to s	it Diass Cap on 3/0 x 34 from 3/7, T20N, R2E – 2 ½" Brass Cap set N & T in SW side P.P. set epoxied tag on top conc. Proset N & T in NW side 14" Maple et N & T in NE side 9" R. Maple NE Cor. Conc. Fndt. of Hse.	in Mon. Box (KJO)	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR

Signed by: Surveyor's Michigan License No.: Date: 39088

No. 39088 POFESSION