LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. S., R. 2 E. W.	C-8; C-7; D-7; E-7
2. PROPERTY CONTROLLING IN SECTION	, T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 23, 19 84, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued

D-7			E-7		
Set DNR monument			Set DNR monument		
7" Jack Pine	S36°E	22.4'	16" Red Pine	South	72.2'
6" Jack Pine	N59°E	44.8'	7" White Birch	N55°W	32.2'
5" Cedar Post	N5°E	25.0'	6" Cedar Post	North	20.0'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-8 - Set corner by proportionate measurement, midway and on line between section corners.

C-7 - Corner previously established in DNR survey 1971.

D-7 - Set corner by proportionate measurement midway and on line between section corners in centerline of road.

E-7 - Set corner by proportionate measurement between fd. DNR mon. for NW corner Section 20 and section corner established at NE corner Section 21. In center of road. No other conclusive evidence was found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8			C-7		
Set DNR monument & cedar post			Found DNR monument		
4" Aspen	N70°E	10.1'	5" Black Ash	S34°E	39.2'
4" White Birch	N26°W	14.7'	4" Red Maple	N27°W	63.0'

SIGNED BY Carl F. Roser 03-13-85 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ GLADWIN COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET