LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. S., R. 2 E. W.	D-11; E-11; E-12;
2. PROPERTY CONTROLLING IN SECTION 32	,T. 19 N. S., R. 2 E. W.	14
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 22, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

E-12

Set DNR Monument & Cedar Post

4" Red Oak	S68°E	1.8'
14" Red Oak	S60°W	16.1'

14

Set 5/8" Bar & Cedar Post

4" Red Oak	S75°E	4.5'
4" Jack Pine	S29°W	29.4'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11 - Set corner by proportionate measurement, midway and on line between section corners.

E-11 - Set corner by proportionate measurement between section corners N and S. Fits with call to stream west.

E-12 - Set corner by proportionate measurement, midway and on line between section corners.

14 - Set corner by standard survey procedure for subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11

Set DNR Monument & cedar post

7" Red Maple	N86°W	27.2'
7" Red Maple	S30°E	7.5'

E-11

Set DNR monument & Cedar Post

4" Red Pine	S73°W	134.6'
5" Red Oak	S5°E	59.9'

SIGNED BY Carl F. Roser 03-13-85 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ GLADWIN COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET