

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>19</u> N. <u>2</u> E. <u>0</u>	<u>D-12;</u>
2. PROPERTY CONTROLLING IN SECTION <u>32</u>	T. <u>19</u> N. <u>2</u> E. <u>0</u>	<u>9; 12; 13</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 18, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 9 - Set corner by standard survey procedure for subdivision of sections.
- D-12 - Set corner by standard survey procedure for subdivision of sections.
- 12 - Set corner by standard survey procedure for subdivision of sections.
- 13 - Set corner by standard survey procedure for subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p style="text-align: center;"><u>9</u></p> <p>Set 5/8" Bar w/cap & Cedar Post</p> <p>7" Aspen S56°W 4.3'</p> <p>5" Aspen S5°W 9.0'</p>	<p style="text-align: center;"><u>D-12</u></p> <p>Set 5/8" Bar w/cap & Cedar Post</p> <p>4" Red Maple S65°W 17.2'</p> <p>8" Red Maple N7°W 12.9'</p>
---	--

<p style="text-align: center;"><u>12</u></p> <p>Set 5/8" Bar w/cap & Cedar Post</p> <p>10" (Twin) Red Maple S15°W 1.8'</p> <p>4" Red Maple N29°W 34.0'</p>	<p style="text-align: center;"><u>13</u></p> <p>Set 5/8" Bar w/cap & Cedar Post</p> <p>7" White Pine N38°E 1.0'</p> <p>5" Aspen S12°E 14.6'</p>
--	---

SIGNED BY Carl F. Roser 03-13-85 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____ GLADWIN COUNTY