

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


GLADWIN COUNTY  
T 19 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 6 & 7

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 5-3-71

WITNESSES TO CORNER..... 27" W.P. Stp. S 81 E 32.3'



18" " WEST 41.4'

20" " S 7 W 7.7'

AND  
20" " N 4 W 23.5'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners.

SURVEYOR'S SEAL

SIGNED *Thomas H. Heston* DATE 5-10-71  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68