


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY  
T 19 N R 1 & 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 1-12-6-7  
CORNER MONUMENT Set Dept. Monument  
DATE MONUMENT PLACED AND WITNESSED 5-3-71

WITNESSES TO CORNER.....	<u>20" W.P. Stump</u>	<u>N 25 E</u>	<u>24.7'</u>
	<u>16" "</u>	<u>N 80 W</u>	<u>12.3' Old NBT</u>
	<u>24" "</u>	<u>S 78 W</u>	<u>21.8'</u>
	<u>AND</u>		
	<u>8" Poplar</u>	<u>S 30 W</u>	<u>15.5'</u>



CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by 1½" pipe and old stake point Nov. 1970. Old W.P. stump  
N.B.T. N80°W.

SURVEYOR'S SEAL

SIGNED *Terrence J. Ostling* DATE 5-10-71  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68