STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		GLADWIN	COUNTY
		T <u>19 N</u>	R <u>2 E</u>
DESCRIPTION OF CORNER	1/4 corner common to Sec	tions 4 & 5	
CORNER MONUMENT	Set Dept. Monument		
DATE MONUMENT PLACED AND	WITNESSED 4-29	-71	
NITNESSES TO CORNER	•		
N	24" W.P. Stp	N 85 W	14.41
5	7" S. Maple	S 25 E	72.31
	AND 14" Triple S. Maple	N 67 E	61.71
CIRCLE CORNER REGISTE			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found November 1970 by retracement survey crew. Found 4"x4" square post as described in C.C.C. survey between 1930 & 1940. Replaced with Dept. Mon.

SURVEYOR'S SEAL

SIGNED

Jenneth Helling

5-6-73

DISTRIBUTION:

REGISTERED LAND SURVEYOR

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing