STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			GLADWIN		COUNTY	
		τ_	19	<u> </u>	R_	2 E_
DESCRIPTION OF CORNER _	Sec. Corner common t	o Sections	4-5-8	-9		
CORNER MONUMENT	Set Dept. Monument					
DATE MONUMENT PLACED AND	WITNESSED	4-29-71				
ITNESSES TO CORNER						
N	24" W. Pine	N	30 W			24.01
5	18" R. Pine	<u> </u>	88 W			11.5'
	AND		<u>. </u>			
CIRCLE CORNER REGISTER	ED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set, as nearly as possible, to the location of an old post described in the C.C.C. survey between 1930 & 1940. Used evidence (old square posts) North, East & West of this corner to set it.

SURVEYOR'S SEAL

SIG

MILLEY LAND SUBVEYOR

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing