


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY
T 19 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 4 & 9
CORNER MONUMENT Set Dept. Monument
DATE MONUMENT PLACED AND WITNESSED 4-29-71
WITNESSES TO CORNER..... 24" W.P. Stp. S 20 W 52.0'



18" W.P. Stp. S 3 W 10.0'
18" W.P. Stp. S 71 E 28.5'
AND
16" W. Pine N 32 W 151'
CIRCLE CORNER REGISTERED (Green) Leans at about 45° towards corner.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found old post bottom as described in C.C.C. Survey notes (between 1930 & 1940).
Also found C.C.C. chainage marker properly related to this point. Replaced with
Dept. Monument.

SURVEYOR'S SEAL

SIGNED

Thomas J. Ostling

DATE

5-6-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR 10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68