

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY


T 19 N R 2 E

DESCRIPTION OF CORNER E 1/16 corner common to Sections 5 & 8

CORNER MONUMENT Set 1 1/2" pipe 2' long

DATE MONUMENT PLACED AND WITNESSED 4-29-71

WITNESSES TO CORNER.....



8" Cedar S 82 W 98.8'

8" Cedar S 53 E 57.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between 1/4 corner West and Section corner East.

SURVEYOR'S SEAL

SIGNED *Carroll H. Estling* DATE 5-6-71  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68