STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | - | GLADWIN | COUNTY |
|--------------------------|------------------------------|---------------|--------|
| | • | T <u>19 N</u> | RE |
| DESCRIPTION OF CORNER | 1/4 corner common to Section | ıs 5 & 8 | |
| CORNER MONUMENT | Set Dept. Monument | | |
| DATE MONUMENT PLACED AND | WITNESSED 4-29-71 | | |
| WITNESSES TO CORNER | | <u></u> | |
| N | 5" Maple in clump of three | S 01 E | 27.51 |
| 5 | 4" Maple | S 40 W | 33.5 |
| | AND | | |
| CIRCLE CORNER REGISTER | ED | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set M.P.O.L. between section corners East & West, 1/2 mile each way.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Comill Hothing

5-6-71

REGISTERED LAND SURVEYOR

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing