


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY
T 19 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 7-8-17-18
CORNER MONUMENT Set Dept. Monument
DATE MONUMENT PLACED AND WITNESSED 5-3-71
WITNESSES TO CORNER.....



8" Maple in clump S 38 W 31.3'
6" Maple N $\frac{1}{2}$ of twin S 53 E 36.8'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement N & S and on average alignment of N-S road for departure.

SURVEYOR'S SEAL

SIGNED *Kenneth Ostling* DATE 5-10-71
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68