

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


GLADWIN COUNTY
T 20 N R 2E

DESCRIPTION OF CORNER Sec. corner common to Sections 32 & 33 on S. Bdy Twp.

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-8-70

WITNESSES TO CORNER.....



16" W. P. Stp. N30W 62.7'

16" W.P Stp. N70E 72.5'

AND

Corner to Sections 4-5 T19NR2E is 26.4' West

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during retracement survey in T19N R2E.
Found 2"x18" pipe in centerline road, bent over by grader, as
established in some previous survey by persons unknown. fits
very well for proportionate measurement for two miles on
S. side Sec. 32 & 33.

SURVEYOR'S SEAL

SIGNED *Timothy J. Dilling* DATE 12-10-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing