


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

GLADWIN COUNTY  
T 20 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 31 & 32  
CORNER MONUMENT Left 3/4" pipe in place  
DATE MONUMENT ~~PLACED~~ WITNESSED 5-3-71  
WITNESSES TO CORNER.....



1/2" Rod in Sq. Conc. Mon N 46 E 41.1'  
Face of Power Pole N 40 W 46.15'  
AND  
1 1/2" Pipe WEST 3.96'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found in line with Centerline of road North-East & West. Slightly West of Centerline of Road South. Oct. 1970

SURVEYOR'S SEAL

SIGNED *Frank J. Osting* DATE 5-10-71  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68