## LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement	of Act 74, Mich. P.A. 1970	
For corners in GLADWIN		•	
(County)	Located In: Co	orner Code ##	
. Public Land Survey	· · · · · · · · · · · · · · · · · · ·	C-1, D-1, E-1	
	T R T R		
	_		
Property Controlling			
in Section			
3. Miscellaneous	-	Regist	er of Deeds Stamp & File Number
Property in Sec.	S T R		<del></del>
L Lot No	Recorded Plat		A B C D E F G H I J K L
			THE PART OF THE PA
		2	
		3	
CAD: 5 500CD	_ , in a field survey onOCTOBER 26	19. <b>93</b>	
to hereby certify that under t	in a field survey on <del></del>	the corner points mentioned	
in lines 1 and 2 above were	in conformance with regulations and rules i	therefore as required in the	
current manual of survey ins	structions of the United States Department of of a Court of Law and/or that the corner points	the interior, bureau or Lanu	
hove were in conformance	with the rules of the Michigan Board of Land S	Surveyors or by a Decree of a	
Court of Law; established	, re-established, monumented, re-monume	nted, recovered, found as	
expressed below:			
NOTE: Not more than 4 on this certificat	corners, all in the same town and rang	e, may be recorded	
on this certificat	<b></b>	15	
A. Description of origina	al monument and accessories and/or su	bsequent restoration:	
,	D-1	E-1	C-1
			"B" CONT IN CURVE, IS 154'±
	ORNER, B.T'S, LINE TREES & TOPOGRAPHY,		WEST. LOCAL SUR USED B.SPIKE TO REESTB. (SP ? TO US) N1/4
	.O. LINE NOTES; UNLESS NOTED IN ITEM "B"		COR OF 5-6, 1950 MSHD SUR
DELOW.)			SHOW'S FD B.SPIKE 133.42' E OF
			FD STONE. CLOSING COR (SEC'S 5
			& 6) SHOULD BE 2.75 CH'S
			(18).5') EAST OF SW S-36(T21N-
B. Description of corner	r evidence found and/or method applied	in restoring or reestablishing co	R1E) PER US GLO SURVEY. priner:
b. Description of conte	D-1	E-1	C-1
	REESTABLISHED N 1/4 COR S-5	REESTABLISHED NE COR S-5 AT	REESTAB. NN COR OF S-5 AT
	MIDWAY AND ON LINE BETWEEN NE	INTER OF LINE BTW. ESTABLISHED	
	A NW SEC COR'S OF S-5. OLD FN		S1/4 COR & SN COR OF S-36,
	CORNER (E-W B.WIRE & WOVEN	(T21M-R2E) & ON AVERAGE LINE	TZIN-RIE AND LINE BETW. FD PK
	WIRE SOUTH) IS 25'± W	OF B.WIRE FENCE REMAINS TO SOUTH. THIS FITS PROPORTIONATE	(IN B.TOP RD INTER OVER STRONG MAG DIP, 2150' SOUTH, POSS SW
	AND 20'± N. E-W TRAIL IS ON North side of Fn. Cor of Deep		S-5) & FD BOAT SPIKE 1.94"
	DRAINAGE DITCH (DITCH S & W)	& 1 MILE S. FENCE COR (FM	SOUTH. THIS IS IN LINE W/CTR
	IS 545°W, 90'± 3'.	REMAINS S & W) IS 10' SOUTH.	OF B.TOP RD SOUTH & 15' N OF
	·		B.TOP RD FQR 135'± W & 10'± N
			OF CTR OF GRAVEL RD LOOKING TO
			EAST. CTR OF M-30CONT ABOVE
C. Description of monu	ment for corner and accessories establis	shed to perpetuate locating the p	position of the corner:
440 TO STORE STATE OF THE PARTY	D-1	E-1	C-1
E OF MICH	SET DNR HON & CEDAR POST.	SET DNR MON & CEDAR POST.	DROVE 1"x 27" GALV, PIPE N/PS
			CAP.
CARL F. ROSER	3" ASH 530°E 13.26'	7" MAPLE 535°E 30.82'	12" MAPLE \$45°E 63.66°
* LAND_	9" CEDAR 525"E 45.00"	3" ASH S05°W 12.28"	17" R.PIME 535"E 93.25' POWER POLE N60"W 84.69'
BURVEYOR	15" CEDAR \$20"W 44.30"	6" MAPLE S25°W 22.24' 3" MAPLE S86°W 18.55'	POWER POLE N60°M 84.69' FD BOLT IN MON BOX FOR SW COR
12028	DNR MON S 1/4 S-36, T21N-R1E S88°11'N 187.29'	3" NAPEE 500"# 10.33	S-36,T21N-R1E S88 11'N 133.37'
AND SURIER	TEST HIL GUY II W 141.527	T21N-R2E S88°06 N 241.20°	
PARTICIPATE SALES			
_	_ 0		
/) 1	700	5 3 T	a :=

Signed by Carl + Roser \_\_ Date \_\_9-27-95 12028 Surveyor's Michigan License No. \_\_\_