

DEG 1 5 1998

SECTION

| | | LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 | | | | Regularie Collice Regularies Country | | | |
|--|---|--|--|------------------------------|--|--|------------------|------------------|--|
| For corners in | | | | 1 | R | eccived f | ଜନ୍ମ ଅବସ୍ | ord the | |
| Gogebic (County) | Located In: | : | Corner Code # | | 4 <u>11</u> | dev o | 1 NOU | Kaier. | |
| 1. Public Land Survey | T <u>45N</u> R <u>40</u> T R T R | | H-9 | | Liber 7 of Corners Ramona Colling, Deputy Register of Deeds Register of Deeds Register of Deeds | | | | |
| 2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_ | TR TR TR TR | | | | | | | | |
| 4. Lot No, Recorde 5. Private Claims | d Plat | | | | вср | E F G | H I | J K | |
| Quarter Corner Sections 22 and 2 | | | | 2 - | 65 | 4 | 3 - | 2 | |
| I, Gary L. Pisoni, in a that under requirements of P.A. 7 in lines 1 and 2 above were in required in the current manual of the Interior, Bureau of Land Manageorner points mentioned in lines 3 the Michigan Board of Land Survere-established, monumented, reco | '4, Michigan P.A. conformance wit survey instruction gement or by a dec 3, 4 and 5 above veryors or by a De | of 1970, the control of the United States of the United States of a Control of a Co | e corner points mention ns and rules therefore ited States Department urt of Law and /or that to formance with the rules court of Law: establishe | ned 5 as 6 of 7 of 8 | | 16 | 1 | - 11 1 | |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | | | | | 30 | | -27 | -262 | |
| Description of original monum Original corner established bearing Trees; | ent and accessoriony Wells Burt, U.S | es and/or su . Deputy Su | ubsequent restoration: Irveyor on July 27, 185 | 13 | | | |] | |
| Yellow Birch Yellow Birch On 4/18/90, Richard L. Drah measurement on line and mi corner position, set a 3" dia as follows: T45N, R40W, 1/ Land corner certificate reco 1990 Bearing Trees: | n 8" nn RLS with the U dway between the meter brass cap er (4, S-22, S-27, 19 | e Southeast mbedded in 190, RLS 21 | corner and the Southw the North blacktop lane 564, from which he est | ft) ner position rest corner | of Section : | 22, and a | t the | 3 es: | |
| Red Maple Red Maple White Birch Ref. Mon. 3 Steel sign po | 16" 14" 16" 1/4"x30" Al.Mon. | N 16° E S 39° W S 01° W North North | 89.05 feet 121.31 feet 85.80 feet 67.69 feet | | | | | | |
| 3. Description of corner evidence | | | 68.22 feet I in restoring or reestable | lishing corr | ner: | | | | |
| Corner destroyed during re-pa From Richard L. Drahns bearin On 8-31-98 reset corner posit Red Maple Red Maple | ig trees of 1990. ion from the existi 16" 14" | ing bearing N 16°E S 39°E | objects: (All measureme 89.05 feet 124.30 feet | | | | e) | | |
| White Birch Ref. Mon. 3 Steel sign po | 16" 1/4"x30" Al.Mon ost 6' | S 01°W . North North | 85.80 feet 67.69 feet 68.22 feet | Richa | EER GRO | alin | 10/27 | 7/98 | |
| Corner record research on file w | rith County Repres | sentative. | | | COUNTY ! | en de la compansión de la | 147% | ľ | |
| Description of monument for of At the corner position set a 5/8 Gogebic County Remonumenta | 3"X30" rebar with | a 3" diame | ter aluminum can inside | a monum | ent box stan | nped as f | ollows; MICH, | in a second | |
| 8-G11 Jay L. Roon | | Date | October 24, 1998 | | and the state of t | TATE OF | er L. | 41 | |
| urveyor's Michigan License No. | | | FORM Approximation | | 3 | | WD WD | 1 汝草 | |