

AUG 0 8 1997

expressed below:

on this certificate.

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office	
Register's Office Gogebic County	85

For corners in		i mig frequireficite of Act 74, months and 1010		TORNE SERVINGS THE TORNESS SERVI
_6	Gogebic (County)	Located In:	Corner Code ##	13 ⁷² day of May A. D. 1997 at 1:55 o'clock
1.	Public Land Survey	T <u>45N.</u> R <u>45W</u> . T R T R T 8	E-5	Par, and reworded la liber 6 of Conners
2.	Property Controlling in Section	S T R S T R		Kamona Collins, Doputy Nocister of Docks
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	Private Claims	8, 9, 16, & 17; T.45		A B C D E F G H J K L
do in cu	Richard L. Dra hereby certify that under lines 1 and 2 above were rrent manual of survey ins	hn in a field survey on May 1, requirements of P.A. 74, Michigan P.A. of e in conformance with regulations and structions of the United States Department of a Court of Law and/or that the corner p	, 19 <u>97</u> 1970, the corner points mentions rules therefore as required in the ent of the Interior, Bureau of Lar	ed 6 18 17 16 15 14 13 nd 7

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Corner established by Austin Burt on August 8, 1851. Original B.T.s --- 10" Hemlock S.65 W. 33 links (21.78') --- 10" Hemlock N.45 E. 6links (3.96') ---

Corner position re-established by Bill Stuth, Wisc. Surveyor in 1984 by mathimatical means on a survey along portions of the State Line. He set a 5" Cedar post at his corner location.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position from the decayed remains of the two original B.T.s. The first is a large series of root holes with fragments of hemlock bark The second one is now a 16-20" hemlock stump decayed to below and wood. ground line.

Cedar post by Stuth bears S.33 W. 1.9ft. from the original corner location.

Research form on file with Gogebic County records.

PEER GROUP APPROVED

Richard L. Drain 5/12/97

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner location I set a 2" by 30" alum. monument with a $3\frac{1}{4}$ " alum. cap stamped to indicate the corner designation. From the monument I established the following new bearing objects: AICHIGA.

	ad L. Drahn				May	Я
6'	Steel sign rail	N.05	Ε.	2.52	ft.	
6"	Red Maple	s.44	W.	33.66	ft.	
6"	Sugar Maple	S.64	Ε.	10.87	ft.	
8"	Sugar Maple	N.38	W.	21.70	ft.	

No. 21564 FED LAND

Date <u>May 8, 1997</u>

10

RICHARD L. DRAHN LAND SURVEYOR