Surveyor's Michigan License No. USFS A-9

Register's Office Gegebic County LAND CORNER RECORDATION CERTIFICATE SECTION Filing Requirement of Act 74, Mich. P.A. 1970 Received for record that For corners in 2/5/ day of July Corner Code # Located In: Gogebic 4. D. 1999 at 1:05 order _m_ and recorded in T<u>45N</u> R<u>46W</u> 1. Public Land Survey & CORNERS Liber 174 08.20 Remono Collins Oppithis T 46N R 46W 2. Property Controlling Register of Desde in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. ____, Recorded Plat _ 4. Lot No. 5. Private Claims Section Corner 4, 5, 32 & 33; T.45-46 N., R.46 W. , 19<u>99</u> in a field survey on July 14, Richard L. Drahn do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in 5 lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, q re-established, monumented, recovered, found as expressed below: 10 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original corner established by John Burt on 8/31/1847. Original bearing trees: N.02° E. 3.00 chains (198.00') 6" Y. Birch 10° N.30° W. 3.12 chains (205.92') B. Ash S.79° E. 24" W. Pine stub 1.98 chains (130.68') S.37° W. 0.66 chains (43.66') Aspen 3 Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner position found marked by a 1" X 4 ½' drill rod and an old 4" X 4" X 4' Cedar post set by surveyors unknown. The position of the corner agrees well with the original distances to recovered quarter corners ½ mile west and 1 ½ miles east, and to the recovered C.C. of sections 4& 5, 30,50 chains south. No evidence remains of the original bearing trees. Due to the close conformity to the original notes and the long local usage, I have determined that this point best represents the corner as set by John Burt on 8/31/1847 Corner research on file with Gogebic County records. C. Description of monument for comer and accessories established to perpetuate locating the position of the corner: At the corner position I set a 2" x 30" aluminum pipe monument with a 3 1/4" stamped aluminum cap and the Following new B.T.s (all measurements taken to a nail in side of tree) Yellow Birch R" N.83° W. 18.27' 9" Sugar Maple S.16° E. 25.13' **Red Maple** 10" N.48° E. 26.32 N.14° E. Steel sign rail 1.88 RICHARD DRAHN LAND SURVEYOR Nα. 21564

174

REVISED MAY 14,1976 PEVISED JAN., 1983 REVISED OCT., 1995

Date