MAR 0 2 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE

Begister's villice

Carabia :

Filing Requ	irement of Act 74, Mich. P.A.	1970		*****			for	19091	. H
Located In:	Corner Code #			A. D.	1 <u>57</u> 19 <u>9</u>	_day 9_at_	ol 2 }}	<u>v e</u> j	'cloc
T <u>46N</u> R <u>43W</u> T R T R	<u>H-3</u>			Mer.	7 ge/	181	.»L	60	RH
TR STR STR STR		·	Regis			Re	gipte	r el	Dèn
ded Plat		A 1	B	СБ	E F	в н	I	J K	_ <u>L</u>
·		_ z	6 	 	┼-╽-	3	-	- 2	-¦
., R.43 W.		3	- - - -	8-		-10)	11-	—12
 74, Michigan P.A. of 197 Iformance with regulations Iformations of the United Sor by a decree of a Court 	O, the corner points mentioned in and rules therefore as required in States Department of the Interior to of Law and /or that the corner	7 8	-1819	20_	21	-15		23	—13 —13 —24
l and 5 above were in co veyors or by a Decree o	nformance with the rules of the factorial of the factoria	, 9	-30	29_	28-	27		26	25
all in the same town and rang	ge, may be recorded	12 13	 -31 	32	33	34		35	—36
by Austin Burt on 9/6/185 [:] "S.10° W. 14 lir "N.02° W. 29 lin	1. Original bearing trees: nks (9.24') nks (19.14')								
	T46N R43W T R T R T R T R T R S T R	T46N R43W H-3 T R T R T R T R T R S	T46N R43W H-3 T R T R T R T R S T R	Located In: Corner Code # T46N R43W H-3 T R T R T R T R S T T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T T R S T R S T R S T T R S T R S T T R S T R S T T T R S T T T T T S T T T T T T T T T T T T T T T	Located In: Corner Code # T46N R43W H-3 T R T R T R T R S	Located In: Corner Code # T46N R43W H-3 T R T R T R T R S T T R S T T R S T T R S T T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R	Located In: Corner Code # T46N R43W H-3 T R T R T R S T R S T R S T R S T R Register of Deeds Stamp Register of Deeds Stamp Register of Deeds Stamp Register of Deeds Stamp A B C D E F C H Register of Deeds Stamp Register of Deeds Stamp Register of Deeds Stamp Register of Deeds Stamp A B C D E F C H A B C D E	Located In: Corner Code # Located In: Located In: Located In: Corner Code # Located In: Located I	Located In: Corner Code # Located In: Corner Code # T48N R43W H-3 T R T R T R S T R S T R S T R S T R Register of Deeds Stamp & File Num Register of Deeds Stamp

I restored the corner position at record bearing and distance from the remains of the two original bearing trees. The first is a badly decayed 12"-16" downed Cedar. The second one is now a downed 14"-18" Cedar.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: At the corner position I set a 2" x 30" aluminum pipe monument with a 3 1/4" stamped aluminum cap and the Following new B.T.s (all measurements taken to a nail in side of tree)

Cedar	.9"	S.39°E.	13.21'
Cedar	13"	N.75° E.	29.011
Cedar	12"	N.30° W.	27.581
Steel sign rail	6'	N.06° W.	1.70

RICHARD L. DRAHN LAND SURVEYOR No.

Date <u>June 20, 1999</u>

Surveyor's Michigan License No.

21564

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SL REVISED MAY 14.1976

USFS #3 E-15

REVISED JAN., 1983 REVISED OCT., 1985