MAR 0 2 2000				·*.	Magrata & t	ettina l	76
	LAND CORNER RECORDATION CERTIFICATE				Kegister's (Gogebic (o	unty ss.	
SECTION For corners in	Filing	Requirement of	Act 74, Mich. P.A. 1	970	12 th	eived for rea	
Gogebic L	ocated in:	Corner Code #				day of M. 9 at 10:49	
1. Public Land Survey	T 4630 44	777		·	A	m., and rec	orded l
1. Public Latiu Survey	T <u>46</u> NR <u>4:</u> TR_	3W <u>K-</u>	4				DRNE
	TR_ TR_				Pannen	2 Collins	. Den
2. Property Controlling S in Section S. Miscellaneous S. Property in Sec. S	TR_ TR TR					Ragister (of Does
o	<u> </u>		- _	Regis	ster of Deeds	Stamp & File	Numbe
4. Lot No, Recorded	Plat			Д		Ситт	12 1
5. Private Claims			···	1 7 6-		G H I J	
Quarter Corner 11				3		3 2	
I, <u>Richard I.</u> <u>Drahn</u> in a requirements of P.A. 74, Michigan P.A.	, of 1970, the corner n	oints mentioned in lin	ne 4 and 2 above upon in	<u> </u>		10-11	
conformance with regulations and rules United States Department of the Interior that the corner points mantiaged in the	r. Bureau of Land Mana	idement or hy a docto	a of a Court of Law and for	1 '	17-16	15-14	1.3
that the corner points mentioned in line Board of Land Surveyors or by a De recovered, found as expressed below:	so, 4 and 5 above wer scree of a Court of La	e in conformance with aw; established, re-e	n the rules of the Michigan established, monumented,	7			
NOTE: Not more than 2 corners, a	I in the same town a	nd range may be re	operated.	8 -19-	20 21	22 23	24
on this certificate.		inditalige, flidy be te		10—30—	29 28	2726	25
				11 12 31	37 33	34 35	+
A Description of the co				13		34 35	
A. Description of original monumer					_		
Corner established East 6 links (3.96	') Ceda	r 14" West	44 links (29	9.04')			
Paul R. Mack on 4/1 placed a location p	10/35 recov	ered the c	edar bearing	tree s	till sc	cibed and	đ
Richard L. Drahn, I 1935 location poste stamped aluminum ca 28.00' 9" Cedar	RLS 21564 rer still at ap and the res.30 E.3	ecovered t tached. H following .54' "	he still blaz e set a 3/4" new B.T.s X" chiseled i	alumin 14" H n a 3'	um rod v	with a 3	1 11 4
B. Description of corner evidence of 13.36' 6' Stee 1	l sign rail	N.54 E. 1	ng or reestablishing con	ner:			
Corner recorded in				n 3/4/	87		
I recovered the mor						_	
9" Downed "X" chiseled i	d Cedar	N.42 E. S.27 E. CkS.80 W.	27.95' 3½' 13.40'	g tree	s as 10]	.Tows:	
c. The original Cedar	B.T. is not	w down and	badly decaye	d bear	ing West	, 29.01	
Corner research on	file with (Gogebic Con	untv records.	sition of the o			
New bearing tr			1 1111111111		-	OF MICH	Nage of the last o
6" Cedar		S.22 E.	15.90'		13/	RICHARD	
		Z	Carrie Marie	્ ્ર	*	L. DRAHN LAND SURVEYOR	*
		Rechard	P. Dealin 51	11/99		No. 21564	
Signed by Richard P.	2) 7	ଓଡ଼	MIN Considerations		The state of the s	IAKO	

USFS G-21

Surveyor's Michigan License No. 21564