## SURVEY & REMONUMENTATION

OCT 0 3 1996

## LAND CORNER RECORDATION CERTIFICATE

Register's Office

COMMISSIO	N Filing Requir	ement of Act 74, Mich. P.A.	•
For corners in  Gogebic  (County)	Located In:	Corner Code ##	Received for record the
Public Land Survey	T 46N R 44W T R T R T R	I-6	A. D. 19 96 at 10.30 o'clock  A m., and recorded in  Liber 5 of Corners  Page 401
Property Controlling     in Section	S T R S T R		Ramona Callins Deputy
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
5. Private Claims  1/4 corner comm  1. John P. Goss  do hereby certify that under required.	o to sec's 14 & 14 and		2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13
current manual of survey instru Management or by a decree of a above were in conformance with Court of Law, established, re expressed below:	ctions of the United States Depar Court of Law and/or that the corne to the rules of the Michigan Board o	Iment of the Interior, Bureau of Laner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found a	5 8 19 20 21 22 23 24 a
on this certificate.			12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on 20th Aug., 1851. Set post. Original bearing trees: Cedar 14" S 85° E 41 links

Hemlock 10" N 42° W 38 links

In June of 1970 Donald Lappala R.L.S. of U.S.F.S. set this corner by single proportionate measurement. It had a very old fence line West from corner and a old fence line East from corner. He recorded this corner in Liber 1 on pages 87 and 88. He established the following bearing trees and reference objects: Spruce- N 65° E- 39.0'; 9" Tamrach- S 38° E- 40.0'; 20" Spruce- S 27° W- 47.3' This Liber is Liber 1 of Land Corners for Gogebic County. B Description of corner evidence found and/or method applied in restoring or reestablishing corner.

D. Lappala set a 2" iron pipe with 3" bronze cap stamped to note corner information.

I found the 2" iron pipe with 3" bronze cap as noted in D. Lappala certification and it checked with his witnesses. I updated the accessories as noted below to state and county specification.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the 2" iron pipe with 3" bronze cap I established the following bearing trees and reference objects. E OF MICHIGAN

10" Spruce	n 65° e	39.01
12" Tamarack	S 380 E	40.021
23" Spruce	S 27° W	47.291
13" Ash	n 50° w	13.82
6' rail & sign	N 04° E	1.51

EO LAND

Surveyor's Michigan License No. \_\_\_

SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971