	the second secon				Register's	Office]		
·		CORNER RECORDA			Cogebic (County \ \ St	L	
For corners in	riing	Requirement of Act	74, MICH. P.A.	1970	P.	eceived for	if recor	d the
Gogebic	Located In:	Corner Code #		•	262	day o	MAG	,
(County)					A. D. #			
1. Public Land Survey	T <u>46NR_4</u>	44W <u>K-3</u>			Liber_ ?	_m., and	records	
	TR_ TR		•		es page ?		1	Y K E
	<u> </u>	SURVEY	! &		Che		Rups	ne
2. Property Controlling in Section	S R_ S T R	—}EM ONUMEN	ITATION'		Deg	2 Regis	ar af [locals
3. Miscellaneous	SR		you.					
Property in Sec.	S IR	JAN 0 5 2	րու	Re	gister of De	eds Stamp	& File N	lumber
4. Lot No, Reco	rded Plat	SECTIO	A	, A E	3 C D E	F G H	IJ	K L
Section Corner,	Sections 1.2.	.11 & 12. T.40	—— 5 N., R.Ы	4 W.2	 	_ {) 	<u> </u>
				4				•
I, John P. Goss requirements of P.A. 74, Michigi	, in a field survey on ME an P.A. of 1970, the corner	arch 8, 19 do he	ereby state that und and 2 above were	in	8-1-8-1	— ˈ9 1 ' 	J— 1 ₁ 1	12-
conformance with regulations and United States Department of the	d rules therefore as required i	in the current manual of sur	ev instructions of t	he ⁵	17	-161		++
that the corner points mentioned Board of Land Surveyors or by	d in lines 3, 4 and 5 above we	ere in conformance with the	rules of the Michiga	an []		16-1-1		13-
recovered, found as expressed be			roriou, moriamonto	8 -1	920	_21 <u>2</u>	223_	24
	ners, all in the same town a	and range, may be record	led	9				
on this certificate.				10 -3	0 29	-282 ⁻	7——26	- 2 5-
				11 12 3	132	_333	135_	36-
				13				
A Description of original mo Corner establish Original bearing	hed by Austin	Burt, on Augu	ist 20,185		.7.821)			
	Cedar	. 8" N 68°	E 20 15	inks (1	3.201)			
Richard L. Drahm from the remains	1, 21004, rest	cored corner poriginal beari	osition a ne trees	at re¥o on Sen	rd bear	ring a	nd di	stan
2" L.D. aluminum	n pipe with 3±	" cap, stampe	ed to indi	lcated	the cor	rner n	nsiti	on.
He established to 8" Black Spruce	one following	reference ob;	ects: 10' Black Snr	' Cedar	- N 12	2 ⁰ W	70.6	4 ft
down; a o. meral	L sign post -	S 20° E - 1.8	it.	• 1	D 19- 1	<u> </u>	0 K4 1	0 - 11
B. Description of corner evidence recorded said	dence found and/or meth i corner in Li	nod applied in restoring of ber 2, page 2	rreestablishing o 236 of Lar	comer: nd Corn	ers on	3-10-	82.	
Found Richard L.	. Drahn, monum	ent and acces	sories.					
Act 74 research	on file.							
NOTE: Drahn monu	ument is a 3/4	inch aluminu	m marsh r	od.				
					DEEL CH			
				Keck	nd P.W			
C. Description of monument	for corner and accessori	es established to perpet	rate locating the	nosition of t		Belle Siki	的人 企业和局	ļ
From found monur R.L.S. 21564, I	ment stamped t	o read: T.46	N. R.44	W.: S-	1.S-2.9	S+11, ; rence	3-12; objec	1981 ts:
14" Cedar 11" Black Spruce	N 12 ⁰	W 70.27 f	t. new na	il		AND THE	OF HICK	Park Physics
8" Spruce	S 800	W 19.90 f	t.		į	5 T L	MN P.	*
6! metal sign p			t. to fac	е		*	LAND	*
(All measurement	taken to nai.	⊥ in side of	tree)		3	SI SI	IRVEYOR No.	18
				-		W. S. F. E.	23509	
Signed by John P L	ر محمد		Date Ma	rch 8,	2000	THE STATE OF	T VIII 3	Service .
Signed by <u>John P L</u> Surveyor's Michigan License I	No23	509						
	US	FS # E-21						