REMONUMENTATION SURVETA

SEP 0 8 1998

## SECTION

Register'	's Office	
Register' Gogebic	County	) SS.

		LAND COR	HEN NECONDALL	ON CERTIFICATE	B .		
Fo	r corners in	Filing Requ	irement of Act 74	4, Mich. P.A. 1970	1422 da	d for record the	
G	ogebic	Located In:	Corner Cod	e <i>#</i>	A. D. 19 98 at	3:10 o'clock	
	(County)				_ P	and recorded in	
1.	Public Land Survey	T46N R 44W	M-5		Liber 6	Of CORNERS	
		T R T4 <u>6N</u> R <u>43</u> W	A-5		Farmena Col	um Deputy	
2.	Property Controlling				R	egister of Deede	
	in Section	S T R					
3.	Miscellaneous Property in Sec.	S T R S T R		Re	egister of Deeds S	amp & File Number	
	Property in Sec.	· · · · · · · · · · · · · · · · · · ·					
4.	Lot No.	, Recorded Plat			- ABCDE	FGHIJK	L
					_		T
					2 6 5	- <del>4</del> - <del>1</del> - <del>3</del> - <del>1</del> - <del>2</del> - <del>1</del> -	· j -
ŗ	Section Corner	: 12, 13, 7 & 18; T	.46 N., R.4	3-44 W.	3		+
				0.0	4 - 7 8 - 1	- 9 10 11	.12- I
ı, Ę	Richard L. Dra	hn in a field survey on Apri	19,	, 19_ <u>98</u>	<b>♦</b>	<del>-   -   -   -   -   -   -   -   -   -  </del>	+
do in	hereby certify that under	rrequirements of P.A. 74, Michigan Free in conformance with regulations	A. or 1970, the corner and rules therefore a	as required in the	6 -18-17-	1 <del>6 </del> 1 <del>5 </del> 14 -	-{3-
Cti	rrent manual of survey in	istructions of the United States De	partment of the Interio	r, Bureau of Land	7		┿
Ma	anagement or by a decree	of a Court of Law and/or that the co	rner points mentioned	l in lines 3, 4 and 5	8 19-20-	212223	-24-
ab	ove were in conformance	e with the rules of the Michigan Boa d. re-established, monumented,	rd of Land Surveyors o re-monumentedreco	or by a Decree of a overed. found as	9	<del></del>	╀
	pressed below:	d, re-established, monumented,	, o monamontos, root	,,,,,,,,	103029	_282726	-25-
N	OTE: Not more than	4 corners, all in the same town	and range, may be	e recorded	11		+
	on this certifica				12 31 32	333435	-36-
		nal monument and accessories			13		
0	34" S.85 W. 2 Spruce 6" S.4: Corner positions Single proportions Stamped aluming 10" 1 13" 8	ished by Austin Bur 20 links (13.20') - 1 E. 42 links (27.7 on re-established k tionate methods. F num cap and the fol Red Maple Sugar Maple Sugar Maple	Spruce 1 /2') Sug by Richard L He set a 2" Llowing new N.31 W. S.81 E. S.15 E.	4" N.62 E. ar 12" N.33 . Drahn (21 X 30" alumi bearing tre	37 links (2 W. 28 link 564) on 10/ num pipe wi	4.42') s (18.48') 22/82 by	
В.	Description of corne	Steel sign rail er evidence found and/or metho	od applied in restori	ng or reestablishin	ng corner;		
		ed in Gogebic Count					
		ch on file with Goo					
]	12" 14" 11"	monument as descri Red Maple Sugar Maple Sugar Maple Steel sign rail	ibed and the N.31 W. S.83 E. S.15 E. N.03 W.	37.59 (n 45.81'	rees as foll new nail) new nail)	ows:	
]	No evidence o	f the original cor	ner or B.T.s	remains.			
C.	Description of mon	ument for corner and accessori	es established to p	erpetuate locating	the position of the	corner:	
]	New bearing t	ree referenced:					
	10"	Twin Sugar Maple	N.34 E.	51.91'	111		

RICHARD L. DRAHN LAND SURVEYOR No. 21564 A LAND

Signed by Richard L.	Dralm
Surveyor's Michigan License No.	

April 12, 1998

\_ Date ...\_