

4. Lot No.

5. Private Claims _

DEC 1	6)	1998
-------	----	------

LAND CORNER RECORDATION CERTIFICATE

States	's Office	
Cogebic	's Office County	88.

		٠,			
30	Rec	eived dav	for r	ecord	the
A. B.	19.98	at_	9:05	o'c	nek
aber_	' '		01 6	ORN	ERS
pag pag	e <i>6</i> (Ma	4			
Kam	Ma	Oni	lima	$\Lambda_{\alpha\alpha}$	


SECTION For corners in			Filing Require	ment of Act 74, Mich. P.A. 197	
	Gogebic (County)	Locat	ed In:	Corner Code ##	A. D. 1998 at 9:05 o'clock
1.	Public Land Survey	T	46NR 45W	A-2)	liber 7 of Corners Reycology Only Decided in
2.	Property Controlling		46N R _46W R B	M-2	Register of Doods
3.		\$ T \$ T	R	F	Register of Deeds Stamp & File Number

Quarter Corner 6 & 1; T.46 N., R.45-46 W.

___ , Recorded Plat _

Richard L. Drahn in a field survey on October 2, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on 9/1/1847. Original B.T.s --- Hemlock 10" S.19 W. 15 links (9.90') --- Y. Birch 30" N.40 E. 5 links (3.30') ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the two original bearing trees. The first is a large windthrown stump hole with Hemlock root and bark fragments. (The only old growth Hemlock remains within a 30' radius.) The second one is now a widespread series of very large root holes with fragments of Yellow Birch bark.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ " stamped aluminum cap and the following new bearing objects: OF MICHIS

10" Yellow Birch S.02 E.

8,241

6" Twin Sugar Maple S.88 W. 8"

8.421

6'

Yellow Birch N.47 E. Steel sign rail S.87 E. 21.55' 2,291

A 3/4" iron pipe and guard post bears N.15 E. 27.5'.

No. 21564 LAND

RICHARD

L. DRAHN

LAND SURVEYOR

Signed by

____ Date __

October 6, 1998

Surveyor's Michigan License No. 21564

USFS C-1

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISEO JAN., 1983